BRITISH COLUMBIA ENERGY REGULATOR

January 13, 2026 Enforcement File: 2025-0115

Logan BC Oil & Gas Corp.
900, 355-4th Avenue SW
Calgary, AB T2P 0J1

Attention: Christine Roberts, Sr Surface Land Coordinator

RE: Warning: Failure to comply with a condition of a Permit

Dear Christine Roberts,

Logan BC Oil & Gas Corp. (Logan BC) holds permit AD 100119301 issued under the *Energy Resource Activities Act*. This permit contains a condition as follows:

> *Archaeology site(s) HbRb-26 and HbRb-27 and areas of potential (AOP) 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, and 12 must be avoided as detailed in the H3M Environmental Archaeological Impact Assessment report, dated April 3, 2025. Temporary fencing must be installed as detailed in the above cited report prior to the commencement of construction activities. The temporary fencing must be removal post-construction. A qualified archaeologist must oversee the installation and removal of the temporary fencing. A qualified archaeologist is defined as a SubarcticBoreal forest field director or Heritage Conservation Act permit holder approved by the Archaeology Branch of MOF...*

In the assessment report dated April 3, 2025, from H3M Environmental, there were two (2) archaeological sites identified, HbRb-26 and HbRb-27, along with twelve (12) areas of potential AOP) noted adjacent to the site boundary. Logan BC avoided the archaeological sites through project redesign of the access right of way. To ensure avoidance of these sites and AOP, it was recommended in the report that snow fencing be installed prior to construction start. This was then confirmed by the Archaeology Mitigation Approval Letter sent from the BCER on May 23, 2025, which listed fencing and mitigation requirements as per the report, and was included as a permit condition.

Between November 10, 2025, and November 12, 2025, Logan BC did commence construction activities without having the temporary fencing installed as per the permit condition. This resulted in soil pile encroachment and machine blade impacts into the AOP.

BRITISH COLUMBIA ENERGY REGULATOR

Given the circumstances, Logan BC is hereby issued a warning for the following:
Logan BC, between November 10, 2025, and November 12, 2025, at or near Fort St, John, in the Province of BC, did fail to comply with a permit condition contrary to section of the section 21(b)(ii) of the *Energy Resource Activities Act*.

If Logan BC has any questions about this matter, please feel free to contact the undersigned.

Sincerely,

<original signed by>

Compliance and Enforcement Officer
British Columbia Energy Regulator

Physical/Courier
6534 100 Avenue
Fort St. John, BC VIJ 4M6

T: 250.794.5200
F: 250.794.5390

www.bc-er.ca