

Date: November 19th, 2018

Canadian Natural Resources Ltd Suite 2500, 855- 2<sup>nd</sup> Street SW Calgary, AB T2P 4J8

Attention: Cindy Grieder, Reclamation Coordinator

Re: <u>Canadian Natural Resources Certificate of Restoration Application (part II) for the</u> Well Site CNRL Et Al Ring C-22-G/94-H-16 (WA # 20624)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 20367) submitted by SynergyAspen Environmental on behalf of Canadian Natural Resources Limited on September 24<sup>th</sup> 2018.

The reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5882).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Canadian Natural Resources Limited remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

Taher Morsi, Ph.D., P.Ag

**Environmental Management Officer** 

Operational Policy & Environment

Resource Development & Stewardship Branch

Telephone: 250-794-5234 Facsimile: 250-794-5390

E-Mail: Taher.Morsi@bcogc.ca

Adrian Renneberg, Synergy Environmental Strategies Inc, 9904 106 Street, Fort CC:


St John, BC, V1J 1V8



## **CERTIFICATION OF RESTORATION APPLICATION FORM - PART 2**

Physical Address: 6534 Airport Road, Fort St. John, B.C. V1J 4M6 Mailing Address: Bag 2, Fort St. John, B.C. V1J2B0

Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature. **COMMISSION USE ONLY** A Document: Commission File No. or AD No.: **ADMINISTRATION** B Well Permit No .: 200 24 Well Name: CNRL ET AL RING C-022-G/094-H-16 Well Location: C-022-G/094-H-16 Petroleum Title (Permit, Lease, Number, etc): Title Holder(s) (Permittee, Lessee, etc): Canadian Natural Resources Limited Surface Landowner: Crown Land Surface Occupant: N/A (Attach Letter of Release) NA (Attach Letter of Release) Applicant's Agent in Field: Duncan McLeod Name: Veronica-Saluk Adrian Rennebera Company: SynergyAspen Environmental Inc. Position: Project Coordinator Address: 9904 106 Street City: Fort St. John Province: BC arenneberg Phone: 250-785-1030 Email: vealuk@synergyaspen.ca Postal Code: V1J 1V8 Fax: 250-785-1034 Agent Signature: Date: April 4, 2018 31500 Application Fee Attached C RESTORATION INFORMATION Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location): The wellsite was 110 m x 85 m and was constructed on forested. Crown land. The access road associated with the wellsite was a winter access road 10m x 123m which joined onto an existing seismic line used for winter access. According to the survey plan dated October 1, 2005, a borrow pit (60 m x 80 m) and a remote sump (60m x 60 m) were proposed with the well location. During the field assessment, it was determined that the remote sump was built as proposed and the borrow pit was never constructed. It is in the opinion of SynergyAspen that the wellsite and associated features have been satisfactorily restored and no further work is required. Details of any areas left unrestored at Landowner's request: Crown Land Was "Approval to Construct" subject to any reclamation conditions? MNO Reclamation Inspection Report included?

Updated: 23-June-2016 Effective: 23-June-2016

Is this location within the Agricultural Land Reserve? If YES, attach Schedule B

YES

APPROV	/AL - FOR	COMMISS	SION LISE	ONLY

D

**CERTIFICATE OF RESTORATION** 

CERTIFICATE NO.

5882

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

NOV 19,2018

Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act and the Environmental Management Act.* Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act.* If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.

Updated: 23-June-2016 Effective: 23-June-2016