

Date: November 29th, 2018

Canadian Natural Resources Ltd Suite 2500, 855- 2nd Street SW Calgary, AB T2P 4J8

Attention: Cindy Grieder, Lead Reclamation

Re: Canadian Natural Resources Certificate of Restoration Application (part II) for the Well Site CNRL Ring A-36-J/94-H-9 (WA # 20635)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 20635) submitted by SynergyAspen Environmental on behalf of Canadian Natural Resources Limited on October 1st, 2018.

The reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5900).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Canadian Natural Resources Limited remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

Taher Morsi, Ph.D., P.Ag Environmental Management Officer Operational Policy & Environment

Resource Development & Stewardship Branch

Telephone: 250-794-5234 Facsimile: 250-794-5390

E-Mail: Taher.Morsi@bcogc.ca

cc: Adrian Renneberg, Synergy Environmental Strategies Inc, 9904 106 Street, Fort St John, BC, V1J 1V8



CERTIFICATION OF RESTORATION APPLICATION FORM – PART 2

Physical Address: 6534 Airport Road, Fort St. John, B.C. V1J 4M6 Mailing Address: Bag 2, Fort St. John, B.C. V1J 2B0 Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY								
Commission File No. or AD No.: Document:								
ADMINISTRATION B								
Well Permit No.: 20635								
Well Name: CNRL RING A- 036-J/094-H-09				Well Location: A- 036-J/094-H-09				
Petroleum Title (Permit, Lease, Number, etc):								
Title Holder(s) (Permittee, Lessee, etc): Canadian Natural Resources Ltd.								
Surface Landowner: Crown Land (Attach Letter of Release) NA				Surface Occupant: N/A (Attach Letter of Release)				
Applicant's Agent in Field:								
Name: Adrian Renneberg								
Company: SynergyAspen Environmental Inc.			F	Position: Environmental Client Manager				
Address: 9904 106 Street City: Fort St. Jo			ohn	Province: BC		BC		
Postal Code: V1J 1V8	ode: V1J 1V8 Phone: 250-785-1030 F		Fax:	: 250-785-1034	Email: arenneberg@synergyaspen.ca		ca	
Agent Signature: Acuales				_	Date:			
\$1500 Application Fee Attack	ned							
RESTORATION INFORMATION CO							C	
Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):								
The wellsite was 110 m x 85 m and was constructed on forested, Crown land. The wellsite was accessed via a 10 m x 777 m winter access road. No soil disturbance occurred on the winter access road. A 60 m x 60 m common remote sump was associated with the well location. A 60 m x 60 m borrow pit was proposed to be built directly northeast of the Site but was not constructed. The wellsite was located out of the boundaries of the Agricultural Land Reserve. It is the opinion of SynergyAspen Environmental Inc. that the wellsite and associated access road have been satisfactorily restored and no further work is required.								
Details of any areas left unrestored at Landowner's request:								
Crown Land								
			ut I					
Was "Approval to Construct" subject to any reclamation conditions?								
Reclamation Inspection Report included?							NO	
Is this location within the Agricultural Land Reserve? If YES, attach Schedule B								

Updated: 23-June-2016 Effective: 23-June-2016

APPROVAL – FOR COMMISSION USE ONLY							
CERTIFICATE OF RESTORATION CERTIFICATE NO. 5900							
This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.							
Approval Date: 10 129, 2018							
Authorized Commission Employee							

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act and the Environmental Management Act.* Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act.* If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.

Updated: 23-June-2016 Effective: 23-June-2016