

December 4, 2023

Enforcement File: 2022 - 0151

ISH Energy Limited  
1200, 308 4th Avenue  
Calgary, AB T2P 0H7

Attention: Earl Ward,

**RE: Warning: Fail to comply with Drilling and Production Regulation, B.C. Reg. 282/2010, Section 41.1.**

Dear Earl Ward,

ISH Energy Limited is the operator and permit holder for numerous wells and facilities, at or near Fort Nelson British Columbia (BC). Permit holders who operate wells and facilities in BC have been required to complete surveys of wells and facilities since leak detection and repair (LDAR) requirements within the Drilling and Production Regulation (DPR) came into effect on January 1, 2020. The specific legislation that compels a permit holder to conduct surveys is contained in Section 41.1 of the DPR.

An evaluation of ISH Energy Limited survey data for wells and facilities for the calendar years 2021 and 2022 indicates that ISH Energy Limited failed to fully comply with section 41.1 of the DPR.

Given the circumstances, ISH Energy Limited is hereby issued a warning only for the following:

ISH Energy Limited, between January 1, 2021 and December 31, 2021, at or near Fort Nelson, in the Province of BC, did fail to complete all the required surveys for both wells and facilities contrary to section 41.1 of the DPR.

If ISH Energy Limited has any questions about this matter, please feel free to contact the undersigned.

Sincerely,

<original signed by>

Compliance and Enforcement Officer  
British Columbia Energy Regulator