

December 1, 2023

Enforcement File: 2022 - 0152

Tourmaline Oil Corporation  
2900, 250 6th Avenue SW  
Calgary, AB T2P 3H7

Attention: Jason Wilshusen,

**RE: Warning: Fail to comply with Drilling and Production Regulation, B.C. Reg. 282/2010, Section 41.1.**

Dear Jason Wilshusen,

Tourmaline Oil Corporation is the operator and permit holder for numerous wells and facilities, at or near Fort St John British Columbia (BC). Permit holders who operate wells and facilities in BC have been required to complete surveys of wells and facilities since leak detection and repair (LDAR) requirements within the Drilling and Production Regulation (DPR) came into effect on January 1, 2020. The specific legislation that compels a permit holder to conduct surveys is contained in Section 41.1 of the DPR.

An evaluation of Tourmaline Oil Corporation survey data for wells and facilities for the calendar years 2021 and 2022 indicates that Tourmaline Oil Corporation failed to fully comply with section 41.1 of the DPR.

Given the circumstances, Tourmaline Oil Corporation is hereby issued a warning only for the following:

Tourmaline Oil Corporation, between January 1, 2021 and December 31, 2021, at or near Fort St. John, in the Province of BC, did fail to complete all the required surveys for both wells and facilities contrary to section 41.1 of the DPR.

Tourmaline Oil Corporation, between January 1, 2022 and December 31, 2022, at or near Fort St. John, in the Province of BC, did fail to complete all the required surveys for wells contrary to section 41.1 of the DPR.

If Tourmaline Oil Corporation has any questions about this matter, please feel free to contact the undersigned.

Sincerely,

<original signed by>

Compliance and Enforcement Officer  
British Columbia Energy Regulator