

December 1, 2023

Enforcement File: 2022 - 0153

Harvest Operations Corporation  
1000, 700 9th Avenue SW  
Calgary, AB T2P 3V4

Attention: Eric Deegan,

**RE: Warning: Fail to comply with Drilling and Production Regulation, B.C. Reg. 282/2010, Section 41.1.**

Dear Eric Deegan,

Harvest Operations Corporation is the operator and permit holder for numerous wells and facilities, at or near Fort St John British Columbia (BC). Permit holders who operate wells and facilities in BC have been required to complete surveys of wells and facilities since leak detection and repair (LDAR) requirements within the Drilling and Production Regulation (DPR) came into effect on January 1, 2020. The specific legislation that compels a permit holder to conduct surveys is contained in Section 41.1 of the DPR.

An evaluation of Harvest Operations Corporation survey data for wells and facilities for the calendar years 2021 and 2022 indicates that Harvest Operations Corporation failed to fully comply with section 41.1 of the DPR.

Given the circumstances, Harvest Operations Corporation is hereby issued a warning only for the following:

Harvest Operations Corporation, between January 1, 2021 and December 31, 2021, at or near Fort St. John, in the Province of BC, did fail to complete all the required surveys for both wells and facilities contrary to section 41.1 of the DPR.

If Harvest Operations Corporation has any questions about this matter, please feel free to contact the undersigned.

Sincerely,

<original signed by>

Compliance and Enforcement Officer  
British Columbia Energy Regulator