

December 4, 2023

Enforcement File: 2023 - 0122

Pacific Canbriam Energy Limited
2100 215 2nd Street SW
Calgary, AB T2P 1M4

Attention: Jeff Pakish,

RE: Warning: Fail to comply with Drilling and Production Regulation, B.C. Reg. 282/2010, Section 41.1.

Dear Jeff Pakish,

Pacific Canbriam Energy Limited is the operator and permit holder for numerous wells and facilities, at or near Fort St John British Columbia (BC). Permit holders who operate wells and facilities in BC have been required to complete surveys of wells and facilities since leak detection and repair (LDAR) requirements within the Drilling and Production Regulation (DPR) came into effect on January 1, 2020. The specific legislation that compels a permit holder to conduct surveys is contained in Section 41.1 of the DPR.

An evaluation of Pacific Canbriam Energy Limited survey data for wells and facilities for the calendar year 2022 indicates that Pacific Canbriam Energy Limited failed to fully comply with section 41.1 of the DPR.

Given the circumstances, Pacific Canbriam Energy Limited is hereby issued a warning only for the following:

Pacific Canbriam Energy Limited, between January 1, 2022 and December 31, 2022, at or near Fort St. John, in the Province of BC, did fail to complete all the required surveys for both wells and facilities contrary to section 41.1 of the DPR.

If Pacific Canbriam Energy Limited has any questions about this matter, please feel free to contact the undersigned.

Sincerely,

<original signed by>

Compliance and Enforcement Officer
British Columbia Energy Regulator