

## Notice of Operation and Completion/Workover Report Reference Guide

This reference guide provides examples of activities that require the submission of Notice of Operation and Completion/Workover Report.

## Notice of Operation:

- A Notice of Operation must be submitted using the online <u>eSubmission portal</u>.
- The Notice of Operation provides the BC Energy Regulator an opportunity to schedule an inspection, awareness of operation for appropriate emergency response and verification for reporting compliance.
- As per Section 24 of the DPR, a Notice of Operation must be submitted at least, 1 business day before beginning any work on the well.

## Completion/Workover Report:

- As per Section 36 (1) of the DPR, a Completion/Workover Report must be submitted within 30 days of the end of each initial completion,
  - completion, workover or suspension operation, with an attached downhole schematic diagram, in color.
- Refer to the eSubmission User Guide, for Required File Naming Convention, and submission methods

COMPLETION AND WORKOVERS	MAINTENANCE
A Notice of Operation including a detailed program complete with a current downhole schematic, <u>in color</u> , is required to be submitted for initial completion, completion, workover and	A <b>Notice of Operation</b> is required to be submitted for the maintenance operations listed below.
suspension operations.	A program and downhole schematic are not required.
A Completion / Workover Report <u>IS REQUIRED</u> to be submitted for the following operations:	A Completion / Workover Report <u>IS NOT REQUIRED</u> for the following operations:
<ul> <li>Completion Operations</li> <li>All cased or open hole operations – using either service and/or drilling rig</li> <li>Perforating</li> <li>Notching of tubing</li> <li>*Fracturing</li> <li>Stimulation</li> <li>Acidization, acid wash (formation cleaning, squeeze, fracturing operations)</li> <li>Re-perforating an existing zone</li> <li>Milling, abrasion jetting (casing, tubing)</li> <li>Barefoot or open hole completion</li> <li>Milling completion equipment</li> </ul> Testing and Monitoring <ul> <li>*DFIT (diagnostic fracture injection test), or Mini-Frac test</li> <li>Injectivity tests</li> </ul> Remedial <ul> <li>Cement squeeze</li> <li>Placement of cement plugs</li> <li>Casing <ul> <li>patch or repair</li> <li>installation of liner</li> <li>removal or replacement</li> </ul> </li> </ul>	Testing, Monitoring and Logging         • *Packer isolation testing         • *Pressure testing – down hole recorders (including gauge build up, fall off and pressure gradient testing)         • Pressure testing – tubing or casing         • Production logging         • Swabbing         • Gauge ring and junk basket runs         • Micro seismic observation (installation of transducers)         Suspension         • Inhibiting wellbore for purpose of suspension         Bottom Hole Equipment – repair, inspection, replacement in-kind or change:         • Artificial lift systems (includes all forms of bottom hole pumping methods)         • downhole pumps (including ESP and PCP)         • plunger lift, including bumper springs         • gas lift         • polish rod         • Sub-surface safety valves         • Check valves         • Downhole chokes (including Installation or removal)         • Recorders
<ul> <li>Fishing</li> <li>Re-Entry         <ul> <li>All completion re-entry work (re-entry of any abandoned well where no additional drilling is to occur).</li> <li>For any workover performed in preparation for a drilling re-entry that is finished prior to and is not to be reported as part of the drilling re-entry (ie: drilling out of or setting of cement plugs, abandonment of hole, recovery or setting of bridge plugs, logging, casing extensions, etc.)</li> </ul> </li> <li>Bottom Hole Equipment         <ul> <li>Installation or removal of:</li> <li>Sub-surface safety valves</li> <li>Packers or plugs, including for well or zone suspensions</li> <li>Artificial lift systems (plunger lift, bumper springs, gas lifts, polish rod, etc)</li> </ul> </li> </ul>	change Note: Submit a single NOO stating that the equipment will be removed and re-installed in a short period of time.  Production Maintenance Chemical operations:  Acid wash or pickling operation  Scale inhibitor  Corrosion inhibitor  Nitrogen / CO2  Methanol  Perforation wash Mechanical operations:  Coil tubing cleanout  Routine wax removal  Subhur removal
<ul> <li>Sliding sleeve – shifting to open or closed</li> <li>Any operations to restore lost hydraulic isolation</li> <li>Tubing, including coiled tubing and velocity strings</li> </ul> Wellhead <ul> <li>Removal of a valve thereby eliminating the ability to isolate the wellbore</li> <li>Installation of a new wellhead to assess an abandoned well leak</li> </ul>	<ul> <li>Sulphur removal</li> <li>Tubing scale cleanout</li> <li>Hydrate removal</li> <li>Wellhead:         <ul> <li>Installation of valves and seals</li> <li>Installation of a back pressure valve</li> </ul> </li> <li>Other:         <ul> <li>Gas venting, blow downs, *flowback, *production testing</li> <li>* Note: Well data submissions are required for these operations.</li> </ul> </li> </ul>

Refer to the Notice of Abandonment & Abandonment Report eSubmission Permit Holder Guide, for information on well abandonment and decommissioning submissions.

Contact: Drilling and Production at Drilling.Production@bc-er.ca or Trudy Clark at 250-794-5258