

July 29, 2026

Enforcement File: 2026-0068

NTE Energy Canada Ltd.
800, 700-9th Avenue SW
Calgary, AB T4N 3V4

Attention: Craig Lane

RE: Warning : Fail To Comply Section 41.1(14)(b) of the Drilling and Production Regulation

Dear Craig Lane,

NTE Energy Canada Ltd.(NTE) , being a permit holder of wells and facilities, was required to conduct surveys for those wells and facilities in operation for the calendar year 2025.

Section 41.1(14) of the Drilling and Production Regulation (DPR) states the following:

A permit holder must

- (a) prepare a leak detection and repair report for each survey carried out during a calendar year of a well or facility of the permit holder, and
- (b) submit the report to the regulator by March 31 of the calendar year after the calendar year to which the report relates.

When no reports had been received from NTE after the March 31, 2026, deadline, the regulator sent non-compliance notice, 2026-0255, to NTE on April 23, 2026 requesting the required reports by May 23, 2026.

After no reports had been received by May 23, 2026, the regulator sent a non-compliance reminder to NTE on May 24, 2026, requesting the required reports again.

On June 17, 2026, the regulator's enforcement group sent an e-mail to NTE asking for an explanation on why no reports had been received after the issuance and time granted to submit the reports under non-compliance notice 2026-0255.

On June 17, 2026, NTE responded by stating they had completed all the surveys and believed their service provider had submitted the proper reports. NTE advised the reports would be submitted. Reports were submitted on June 17, 2026, but the submission was incomplete. After further correspondence between NTE and the regulator, NTE completed final submission on July 22, 2026.

Given the circumstances, NTE is hereby warned for the following:

NTE, at or near Fort Nelson , in the Province of BC, on or about April 1, 2026, being a permit holder required to prepare a leak detection and repair report for each survey carried out during a calendar year of a well or

facility of the permit holder, did fail to submit the reports to the regulator of the calendar year after the calendar year to which the report relates, namely by March 31, 2026 for the calendar year 2025, contrary to section 41.1(14)(b) of the DPR.

If NTE has any questions about this matter, please feel free to contact the undersigned.

Sincerely,

<original signed by>

Manager, Enforcement
British Columbia Energy Regulator