

October 31, 2023.

Enforcement File 2022-0031

Pacific Canbriam Energy
2100, 215 2nd Street SW
Calgary, Alberta
Canada T2P 1M4

Attention: Nauman Rasheed, COO

RE: Drill a well without an approved ERP

Dear Mr. Rasheed

On April 6th, 2022, Pacific Canbriam Energy (PCE) notified the BC Oil and Gas Commission (now known as the BC Energy Regulator (BCER)) that PCE had drilled 4 wells on the d-76-H pad without a valid Emergency Response Program (ERP).

An investigation by the BCER determined that PCE was aware of the requirements of having an ERP prior to commencing any drilling operations but did not have one in place. PCE has notified the BCER that going forward, there will be information added to their Drilling Program that will state the following “no drilling is to take place without reviewing and confirming the ERP.”

The investigation determined that on or before April 6th, 2022, Pacific Canbriam Energy did fail to comply with Section 6 (b) of the *Emergency Management Regulation*.

Thereby, Pacific Canbriam Energy is being issued a warning for failing to comply with Section 6 (b) of the *Emergency Management Regulation*

If Pacific Canbriam Energy has any questions about this matter, please feel free to contact the undersigned.

Sincerely,

<original signed by>

Compliance and Enforcement Officer
BC Energy Regulator