

Date: January 17th, 2020

EOG Oil & Gas Canada Inc.
1300-700- 9th Ave SW
Calgary, AB T2P 3V4

Attention: Mathew Ewanchuk

Re: EOG Oil & Gas Canada Certificate of Restoration Application (Part-II) for the Well Site ECOG Rigel 07-20-88-17 W6M (WA # 11343)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report (**Schedule B**) for wellsite for the above referenced well authorization (WA # 11343) submitted by Summit Liability Solutions Ltd on behalf of EOG Oil & Gas Canada Inc. on December 23rd, 2019.

Based upon review of the information provided by the applicant, the reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 6072).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."


And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore EOG Oil & Gas Canada Inc. remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,



Taher Morsi, Ph.D., P.Ag

Environmental Management Officer
Resource Development & Stewardship Branch
Operational Policy & Environment
Telephone: 250-794-5234
Facsimile: 250-794-5390
E-Mail: Taher.Morsi@gov.bc.ca

cc: Alfreod Carcamo, Summit Liability Solutions Ltd, 855-42 Ave SE, Calgary, AB
T2G1Y8

**CERTIFICATION OF RESTORATION
APPLICATION FORM – PART 2**

Physical Address: 6534 Airport Road,
Fort St. John, B.C. V1J 4M6
Mailing Address: Bag 2, Fort St. John, B.C.
V1J 2B0
Phone: (250) 794-5200

RECEIVED

DEC 23 2019

BC Oil and Gas Commission

THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY**A**

Commission File No. or AD No.:

Document:

ADMINISTRATION**B**Well Permit No.: **11343**Well Name: **EOG Rigel 7-20-88-17 W6M**

Well Location: 07-20-088-17 W6M

Petroleum Title (Permit, Lease, Number, etc):

Title Holder(s) (Permittee, Lessee, etc): *EOG Oil & Gas Canada Ltd.*

Surface Landowner: Norbert Siemer

Surface Occupant: N/A

(Attach Letter of Release)

(Attach Letter of Release)

Applicant's Agent in Field

Name: Alfredo Carcamo

Company: Summit Liability Solutions Ltd

Position: Soil Scientist

Address: 855 42 Ave SE

City: Calgary

Province: Alberta

Postal Code: T2G 1A8

Phone: 403 9992623

Fax: 403-802-3684

Email: alfredo@amberenviro.com

Agent Signature: 

Date: 2019 DEC 18

☒

\$1500 Application Fee Attached

RESTORATION INFORMATION**C**

Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):

Wellsite (120 m x 120 m) and access road (745 m) have been fully reclaimed. The former lease and access road are situated within cultivated lands. It was indicated on the survey plan that the access road would run through a forested area, however it was built on the east side of the trees within the cultivated area and reclaimed as cultivated.

Vegetation and soils were assessed and found to be comparable to the surrounding area (offsite).

Details of any areas left unrestored at Landowner's request:

No areas were left unrestored. The owner has stated that he is happy with the current site conditions.

Was "Approval to Construct" subject to any reclamation conditions?

☐ YES☒ NO

Reclamation Inspection Report included?

☒ YES☐ NO

Is this location within the Agricultural Land Reserve? If YES, attach Schedule B

☒ YES ☐ NO

APPROVAL – FOR COMMISSION USE ONLY

D

CERTIFICATE OF RESTORATION

CERTIFICATE NO.

6072

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

Jan 17, 2020

Lat M
Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act and the Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.