

Date: October 4<sup>th</sup>, 2016

EnCana Corporation  
150-9<sup>th</sup> Avenue SW, P.O. Box 2850  
Calgary, AB T2P 2S5

Attention: Diana Dunn, Environmental Advisor

Re: EnCana Corporation Certificate of Restoration Application (Part-II) for the Well Site ECA Swan C-38-I/93-P-8 (WA # 12216)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 12216) submitted by Gemini Environmental Solutions Ltd on behalf of EnCana Corporation on September 30<sup>th</sup>, 2016.

The reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5637).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

**"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."**


And:

**"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."**

Therefore potential liability related residual contamination from the subject oil and gas activity remains the responsibility EnCana Corporation.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

A handwritten signature in black ink, appearing to read "Taher Morsi". The signature is written in a cursive style with a long, sweeping underline that extends to the right.

---

Taher Morsi, Ph.D., P.Ag  
Environmental Management Officer  
Telephone: 250-794-5234  
Facsimile: 250-794-5380

E-Mail: [Taher.Morsi@bcogc.ca](mailto:Taher.Morsi@bcogc.ca)

cc: Nicole Stark, Gemini Environmental Solutions Ltd, 10543 100 Street, Fort St  
John, BC, V1J 3Z4



**CERTIFICATION OF RESTORATION**

**APPLICATION FORM – PART 2**

Physical Address: 6534 Airport Road,  
Fort St. John, B.C. V1J 4M6  
Mailing Address: Bag 2, Fort St. John, B.C.  
V1J 2B0  
Phone: (250) 794-5200

Date Received

THIS IS AN AUDITABLE DOCUMENT

*This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.*

**COMMISSION USE ONLY**

**A**

Commission File No. or AD No.:

Document:

**ADMINISTRATION**

**B**

Well Permit No.: **12216**

Well Name: **ECA Swan**

Well Location: **c-38-I/93-P-8**

Petroleum Title (*Permit, Lease, Number, etc*):

Title Holder(s) (*Permittee, Lessee, etc*): **Encana Corporation**

Surface Landowner: **John Andrew Ellingson**  
(*Attach Letter of Release*)

Surface Occupant:  
(*Attach Letter of Release*)

Applicant's Agent in Field

Name: **Nicole Stark**

Company: **Encana Corporation**

Position **Project Manager**

Address: **10543 100 Street**

City: **Fort St. John**

Province: **BC**

Postal Code: **V1J 3Z4**

Phone: **250-263-9155**

Fax: **250-263-9156**

Email: **nstark@geminicorp.ca**

Agent Signature:



Date: September 20, 2016

\$1500 Application Fee Attached

**RESTORATION INFORMATION**

**C**

Description of Area(s) Restored (*Location, Remote Sump, Access and other disturbed areas affiliated with this location*):

**The wellsite and the east-west portion of the access road have been reclaimed.**

Details of any areas left unrestored at Landowner's request:

**At the landowners request, the northeast to southwest portion of the access road and steel gates have been left in place (see attached landowner consent form).**

Was "Approval to Construct" subject to any reclamation conditions?

YES  NO

Reclamation Inspection Report included?

YES  NO

Is this location within the Agricultural Land Reserve? *If YES, attach Schedule B*

YES  NO

APPROVAL – FOR COMMISSION USE ONLY

D

CERTIFICATE OF RESTORATION

CERTIFICATE NO.

5637

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date: \_\_\_\_\_

\_\_\_\_\_  
*Authorized Commission Employee*

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act and the Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.