



Date: January 23<sup>rd</sup>, 2019

Bellatrix Exploration Ltd  
1920, 800-5<sup>th</sup> Ave S.W  
Calgary, AB T2P 3T6

Attention: Jill Clarke

Re: Bellatrix Exploration Certificate of Restoration Application (Part-II) for the Well Site Bellatrix Et Al Tooga C-28-D/94-P-2 (WA # 13703)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 13703) submitted by Matrix Solutions Inc on behalf of Bellatrix Exploration Ltd on December 10<sup>th</sup>, 2018.

The reclamation assessment report was reviewed and found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5929).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

**"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."**


And:

**"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."**

Therefore Bellatrix Exploration Ltd remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-234

Sincerely,

A handwritten signature in black ink, appearing to read 'Taher Morsi', with a horizontal line underneath.


Taher Morsi, Ph.D., P.Ag  
Environmental Management Officer  
Operational Policy & Environment  
Resource Development & Stewardship Branch  
Telephone: 250-794-5234  
Facsimile: 250-794-5380

E-Mail: [Taher.Morsi@bcogc.ca](mailto:Taher.Morsi@bcogc.ca)

cc: Sara Brown, Matrix Solutions Inc, 11312-100 Avenue , Fort St John, BC,  
V1J1Z9

**CERTIFICATION OF RESTORATION  
APPLICATION FORM – PART 2**

Physical Address: 6534 Airport Road,  
Fort St. John, B.C. V1J 4M6  
Mailing Address: Bag 2, Fort St. John, B.C.  
V1J 2B0  
Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

*This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.*

**COMMISSION USE ONLY****A**

Commission File No. or AD No.:

Document:

**ADMINISTRATION****B**

Well Permit No.: 13703

Well Name: BELLATRIX ET AL TOOGA C-028-D/094-P-02

Well Location: c-028-D/094-P-02

Petroleum Title (Permit, Lease, Number, etc): Not Applicable

Title Holder(s) (Permittee, Lessee, etc): Bellatrix Exploration Ltd.

Surface Landowner: British Columbia Crown land

(Attach Letter of Release)

Surface Occupant: Not Applicable

(Attach Letter of Release)

Applicant's Agent in Field

Name: René Labbé

Company: Matrix Solutions Inc.

Position: Senior Soil Scientist; Reclamation Specialist

Address: Suite 600, 214 - 11 Ave. SW

City: Calgary

Province: Alberta

Postal Code: T2R 0K1

Phone: 403.206.0575

Fax: 403.263.2493

Email: rlabbe@matrix-solutions.com

Agent Signature:

Date: November 21, 2018

☒ \$1500 Application Fee Attached**RESTORATION INFORMATION****C**

Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):

Well site, access road and borrow pit

Details of any areas left unrestored at Landowner's request:

None

Was "Approval to Construct" subject to any reclamation conditions?

☐ YES ☒ NO

Reclamation Inspection Report included?

☒ YES ☐ NO

Is this location within the Agricultural Land Reserve? If YES, attach Schedule B

☐ YES ☒ NO

Updated: 23-June-2016

Effective: 23-June-2016

Page 1 of 2

## APPROVAL – FOR COMMISSION USE ONLY

D


## CERTIFICATE OF RESTORATION

CERTIFICATE NO.

5929

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

Jan 23<sup>rd</sup>, 2019  
Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act* and the *Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.