

Date: September 9th, 2019

Advantge Oil & Gas Ltd 300, 400-2nd Ave SW Calgary, AB T2P 5E9

Attention: Reg Beck

Re: Advantage Oil and Gas Certificate of Restoration Application (Part-II) for the Well Site Advantage Attachie 14-35-84-23 W6M (WA # 14006)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment (Schedule B) Report for wellsite (Never Drilled) for the above referenced well authorization (WA # 14006) submitted by Ecoventure Inc. on behalf of Advantage Oil & Gas Ltd on September 3rd 2019.

Based upon review of the information provided by the applicant, the reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5997).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore potential liability related residual contamination from the subject oil and gas activity remains the responsibility Advantage Oil & Gas Ltd.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

Taher Morsi, Ph.D., P.Ag

Environmental Management Officer

Telephone: 250-794-5234 Facsimile: 250-794-5380

E-Mail: Taher.Morsi@bcogc.ca

cc: Chris Newton, Ecoventure Inc., 220-41 Royal Vista Drive NW, Calgary, AB T3R 0H9



CERTIFICATION OF RESTORATION APPLICATION FORM – PART 2

Physical Address: 6534 Airport Road, Fort St. John, B.C. VIJ 4M6 Mailing Address: Bag 2, Fort St. John, B.C. VIJ 2B0 Phone: (250) 794-5200 SEP 03 2019

BC Oil and Gas Commission

THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

registered as a member in good sta	muling with an organ	THE RESERVE TO THE RESERVE THE	N USE ONLY	usii Columbia	legislature.	Λ	
Commission File No. or AD No.		COMMISSIO				A	
Commission File No. or AD No.).: 	ADMINIS	Document:			В	
Well Permit No.: 14006							
Well Name: ADVANTAGE A	Well Location	Well Location: 14-35-084-23 W6M					
Petroleum Title (Permit, Lease	e. Number, etc):			36			
Title Holder(s) (Permittee, Les		age Oil & Gas Ltd	d.				
Surface Landowner: Crown (Attach Letter of Release)			Surface Occupant: N/A (Attach Letter of Release)				
Applicant's Agent in Field: Eco	venture Inc.						
Name: Carlos Arregoces							
Company: Ecoventure Inc.			Position: Cor	Position: Conservation & Reclamation Discipline Lead			
Address: 220-41 Royal Vista Drive NW City: Calgary					Province: Alberta		
Postal Code: T3R 0H9				40	Email: carlos.arregoces@ecoventure.ca		
Agent Signature: \$1500 Application Fee Attached					Date: August 30, 2019		
		RESTORATION	INFORMATION			С	
Description of Area(s) Restore	ed (Location, Remo	te Sump, Access a	nd other disturbed a	reas affiliated	with this location):		
Constructed never drilled well	site, access road	, borrow pits and	campsite.				
Details of any areas left unres	tored at Landown	er's request:	,				
Morsi. The naturalization of the	e borrow pits was osoil windrow wou	accepted as rec lld also require si	lamation of these gnificant reclamat	areas would ion with the	issed with BC OGC representative I result in further impacts to wetlar destruction of established vegetat	nds and	
Was "Approval to Construct" subject to any reclamation conditions?						□NO	
Reclamation Inspection Report included?						□NO	
Is this location within the Agricultural Land Reserve? If YES, attach Schedule B						□NO	

Updated: 23-June-2016 Effective: 23-June-2016

APPROVAL - FOR COMMISSION USE ONLY

D

CERTIFICATE OF RESTORATION

CERTIFICATE NO.

5997

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

ep 9th 2019

Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the Petholeum and Natural Gas Act and the Environmental Management Act. Under certain circumstances, some information may be released subject to the provisions of the Freedom of Information and Protection of Privacy Act. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.

Updated: 23-June-2016 Effective: 23-June-2016