

Date: January 19th, 2017

Nexen Energy Inc
801 7th Ave S.W
Calgary, AB T2P 3P7

Attention: David Edwards

Re: Nexen Energy Certificate of Restoration Application (Part-II) for the Well Site Nexen Energy TH Hay D-36-D/94-I-16 (WA # 15644)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 15644) submitted by Secure Energy Services Inc on behalf of Nexen Energy Inc on December 21st, 2016.

The reclamation assessment report and additional information reviewed and found that the site has fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5675).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."


And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Nexen Energy Inc remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-234

Sincerely,

A handwritten signature in black ink, appearing to read 'Taher Morsi', written over a horizontal line.

Taher Morsi, Ph.D., P.Ag
Environmental Management Officer
Telephone: 250-794-5234
Facsimile: 250-794-5380

E-Mail: Taher.Morsi@bcogc.ca

cc: Nikki Chartrand, Secure Energy Services Inc, 120-8832 Blackfoot Trail
SW, Calgary, Albert T2J-3J1



CERTIFICATION OF RESTORATION APPLICATION FORM – PART 2 Physical Address: 6534 Airport Road, Fort St. John, B.C. V1J 4M6 Mailing Address: Bag 2, Fort St. John, B.C. V1J 2B0 Phone: (250) 794-5200	Date Received
---	---------------

THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY		A
Commission File No.:	Document:	
ADMINISTRATION		B
Well Permit No.: 15644		
Well Name: NEXEN ENERGY TH HAY D-36-D/94-I-16		Well Location: 200/d-036-D/094-I-16/0
Petroleum Title (Permit, Lease, Number, etc): OGC File # 9602807		
Title Holder(s) (Permittee, Lessee, etc): Nexen Energy ULC		
Surface Landowner: Crown Land <i>(Attach Letter of Release)</i>	Surface Occupant: N/A <i>(Attach Letter of Release)</i>	
Applicant's Agent in Field		
Name: Nikki Chartrand		
Company: SECURE Energy (OnSite Services) Inc.		Position: Project Coordinator
Address: 120, 8832 Blackfoot Trail SE	City: Calgary	Province: AB
Postal Code: T2J 3J1	Phone: 403-930-8535	Fax: 403-720-6007
Email: nchartrand@secure-energy.com		
Agent Signature: <i>N. Chartrand</i>		Date: December 14, 2016
<input checked="" type="checkbox"/> \$1500 Application Fee Attached		

RESTORATION INFORMATION		C
Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):		
The wellsite (1.00 ha), campsite (0.35 ha), log deck (0.18 ha), and remote sump (0.49 ha) are restored.		
The campsite, log deck, and remote sump are all located within c-23-A/94-I-15.		
Details of any areas left unrestored at Landowner's request:		
No areas were left unrestored.		
Was "Approval to Construct" subject to any reclamation conditions?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Reclamation Inspection Report included?		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Is this location within the Agricultural Land Reserve? If YES, attach Schedule B		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

CERTIFICATE OF RESTORATION


CERTIFICATE NO.

5675

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

Jan 19th, 2017



Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act* and the *Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.