

Date: April 23rd, 2019

Canlin Energy Corporation
Suite #2600, 237 – 4th Avenue SW
Calgary, Alberta
T2P 4K3

Attention: Jonathan Mast, Remediation Coordinator

Re: Canlin Energy Corporation Certificate of Restoration Application (part II) for the Well Site Canlin Hoffard D-38-J/94-J-09 (WA # 15685)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 15685) submitted by SNC-Lavalin on behalf of Canlin Energy Corporation on March 25th, 2019.

The reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5967).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."


And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Canlin Energy Corporation remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

A handwritten signature in black ink, appearing to read 'Taher Morsi', with a long horizontal line extending to the left.

Taher Morsi, Ph.D., P.Ag
Environmental Management Officer
Environmental Management & Reclamation Department
Operational Policy & Environment
Telephone: 250-794-5234
Facsimile: 250-794-5380

E-Mail: Taher.Morsi@gov.bc.ca

cc: Kathleen Juneau, SNC-Lavalin Environmental Inc, #202-10012- 97th Avenue,
Fort St John, BC, V1J5P3

**CERTIFICATION OF RESTORATION
APPLICATION FORM – PART 2**

Physical Address: 6534 Airport Road,
Fort St. John, B.C. V1J 4M6
Mailing Address: Bag 2, Fort St. John, B.C.
V1J 2B0
Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY				A
Commission File No. or AD No.:		Document:		
ADMINISTRATION				B
Well Permit No.: 15685				
Well Name: CANLIN HOFFARD D-038-J/094-J-09		Well Location: d-38-J/94-J-9		
Petroleum Title (Permit, Lease, Number, etc): OGC File; Not Available				
Title Holder(s) (Permittee, Lessee, etc): Canlin Energy Corporation				
Surface Landowner: Crown <i>(Attach Letter of Release)</i>		Surface Occupant: N/A <i>(Attach Letter of Release)</i>		
Applicant's Agent in Field: Alana Ross, C.Tech. – SNC-Lavalin Inc.				
Name: Jonathon Mast, B.Sc., P.Ag.				
Company: Canlin Energy Corporation		Position: Reclamation Coordinator		
Address: Suite 2600, 237 4th Avenue S.W.		City: Calgary		Province: Alberta
Postal Code: T2P 4K3	Phone: 403-351-9435	Fax: 403-266-6684	Email: Jonathon.mast@canlinenergy.com	
Agent Signature: <i>[Signature]</i> ON BEHALF OF ALANA ROSS			Date: 2019/03/25	
<input checked="" type="checkbox"/> \$1500 Application Fee Attached				

RESTORATION INFORMATION		C
Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):		
The site and associated borrow pit, remote DWDA, and campsite are located on Crown land. The site's status is "Abandoned".		
The site is now suitable for a Certificate of Restoration Part 2 Approval.		
Details of any areas left unrestored at Landowner's request:		
N/A		
Was "Approval to Construct" subject to any reclamation conditions? – Nothing found in OGC file.		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Reclamation Inspection Report included?		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Is this location within the Agricultural Land Reserve? <i>If YES, attach Schedule B</i>		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

CERTIFICATE OF RESTORATION

CERTIFICATE NO.

5967

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

April 23, 2019

Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act* and the *Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.