

Date: January 23rd, 2017

Canadian Natural Resources Ltd Suite 2500, 855- 2nd Street SW Calgary, AB T2P 4J8

Attention: Ryan Okada, Lead Reclamation

Re: <u>Canadian Natural Resources Certificate of Restoration Application (part II) for the</u> Well Site CNRL Et Al Ring A-7-A/94-H-16 (WA # 15781)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 15781) submitted by SynergyAspen Environmental on behalf of Canadian Natural Resources Limited on December 30^h, 2016.

The reclamation assessment report reviewed and found that the site has fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5681).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Applications & Operations Division Environmental Management and Reclamation Department MAILING 6534 Airport Rd Fort St John BC V1J 4M6

T 250.794-5200 www.bcogc.ca F 250.794-5380 Therefore Canadian Natural Resources Limited remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,


Taher Morsi, Ph.D., P.Ag Environmental Management Officer Telephone: 250-794-5234 Facsimile: 250-794-5380

E-Mail: Taher.Morsi@bcogc.ca

cc: Tanya Allen, Synergy Environmental Strategies Inc, 9904 106 Street, Fort St John, BC, V1J 1V8



CERTIFICATION OF RESTORATION APPLICATION FORM – PART 2 Physical Address: 6534 Airport Road, Fort St. John, B.C. VIJ 4M6 Mailing Address: Bag 2, Fort St. John, B.C. VIJ 2B0 Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

 This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c.

 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

 COMMISSION USE ONLY
 A

Commission File No.:	Document: ADMINI	STR	RATION	В		
Well Permit No.: 15781		L A CA				
Well Name: CNRL ET AL RING A-007-A/094-H-16			Well Location: A-007-A/094-H-16			
Petroleum Title (Permit, Lease,	Number, etc):					
Title Holder(s) (Permittee, Lessee, etc): Canadian Natural Resources Limited						
Surface Landowner: N/A (Altach Letter of Release)			Surface Occupant: N/A (Allach Leller of Release)			
Applicant's Agent in Field						
Name: Tanya Allen, B.Sc., P.Ag.						
Company: SynergyAspen Environmental			Position: Technical Reclamation Advisor			
Address: 9904 106 th St. City: Fort St. John			Province: BC			
Postal Code: V1J 1V8	Phone: 250-785-1030	Fa	ax: 250-785-1034	Email: tallen@synergyaspen.ca		
Agent Signature:	SH COLUMB 1709 Tanya Allen PAg. PAg.		Date: December 20, 2016			

\$1500 Application Fee Attached

RESTORATION INFORMATION

Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):

The wellsite is 120 m x 120 m in size and is located outside the agricultural land reserve on Crown land. A 60 m x 60 m borrow pit and a 40 m x 60 m remote sump were constructed in association with the Site. Winter access to the lease utilized existing seismic lines. No other ancillary sites were constructed or affiliated with the wellsite. It SynergyAspen's opinion that the wellsite and associated ancillary sites have been satisfactorily restored and that no further work is required at the Site.

Details of any areas left unrestored at Landowner's request:

N/A

Updated: 20 January 2014 Effective: 6 February 2014 1

С

Was "Approval to Construct" subject to any reclamation conditio	□yes ⊠no				
Reclamation Inspection Report included?	XYES NO				
Is this location within the Agricultural Land Reserve? If YES, atta	TYES NO				
APPROVAL – FOR COMMISSION USE ONLY					
CERTIFICATE OF RESTORATION	CERTIFICATE NO.	5681			
This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.					
The personal information requested on this form is collected under the a Gas Act and the Environmental Management Act. Under certain circums Freedom of Information and Protection of Privacy Act. If you have any q Corporate Services Branch, Records Administrator, in Fort St. John at the Corporate Services Branch, Records Administrator, in Fort St. John at the construction of the service of	stances, some information may be uestions about the collection, use o	released subject to the provisions of the			

ł

e.*

ł