

Date: January 23rd, 2019

Bellatrix Exploration Ltd
1920, 800-5th Ave S.W
Calgary, AB T2P 3T6

Attention: Jill Clarke

Re: Bellatrix Exploration Certificate of Restoration Application (Part-II) for the Well Site Bellatrix Et Al Tooga B-46-D/94-P-2 (WA # 18002)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 18002) submitted by Matrix Solutions Inc on behalf of Bellatrix Exploration Ltd on December 10th, 2018.

The reclamation assessment report was reviewed and found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5930).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."


And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Bellatrix Exploration Ltd remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-234

Sincerely,

A handwritten signature in black ink, appearing to read 'Taher Morsi', written over a horizontal line.

Taher Morsi, Ph.D., P.Ag
Environmental Management Officer
Operational Policy & Environment
Resource Development & Stewardship Branch
Telephone: 250-794-5234
Facsimile: 250-794-5380


E-Mail: Taher.Morsi@bcogc.ca

cc: Sara Brown, Matrix Solutions Inc, 11312-100 Avenue , Fort St john, BC,
V1J1Z9



**CERTIFICATION OF RESTORATION
APPLICATION FORM – PART 2**

Physical Address: 6534 Airport Road,
Fort St. John, B.C. V1J 4M6
Mailing Address: Bag 2, Fort St. John, B.C.
V1J 2B0
Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY			A
Commission File No. or AD No.:		Document:	
ADMINISTRATION			B
Well Permit No.: 18002			
Well Name: BELLATRIX ET AL TOOGA B-046-D/094-P-02		Well Location: b-046-D/094-P-02	
Petroleum Title (<i>Permit, Lease, Number, etc</i>): Not Applicable			
Title Holder(s) (<i>Permittee, Lessee, etc</i>): Bellatrix Exploration Ltd.			
Surface Landowner: British Columbia Crown land <i>(Attach Letter of Release)</i>		Surface Occupant: Not Applicable <i>(Attach Letter of Release)</i>	
Applicant's Agent in Field			
Name: René Labbé			
Company: Matrix Solutions Inc.		Position: Senior Soil Scientist; Reclamation Specialist	
Address: Suite 600, 214 - 11 Ave. SW		City: Calgary	Province: Alberta
Postal Code: T2R 0K1	Phone: 403.206.0575	Fax: 403.263.2493	Email: rlabbe@matrix-solutions.com
Agent Signature:		Date: November 21, 2018	
<input checked="" type="checkbox"/> \$1500 Application Fee Attached			

RESTORATION INFORMATION			C
Description of Area(s) Restored (<i>Location, Remote Sump, Access and other disturbed areas affiliated with this location</i>):			
Well site, access road, and borrow pit			
Details of any areas left unrestored at Landowner's request:			
None			
Was "Approval to Construct" subject to any reclamation conditions?			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Reclamation Inspection Report included?			<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Is this location within the Agricultural Land Reserve? <i>If YES, attach Schedule B</i>			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

CERTIFICATE OF RESTORATION


CERTIFICATE NO.

5930

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

Jan 23rd 2014



Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act* and the *Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.