

Date: October 29th, 2019

Canadian Natural Resources Ltd Suite 2500, 855- 2<sup>nd</sup> Street SW Calgary, AB T2P 4J8

Attention: Cindy Grieder, Lead Reclamation

## Re: <u>Canadian Natural Resources Certificate of Restoration Application (part II) for the</u> Well Site CNRL Gutah B-41-A/94-H-14 (WA # 18355)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 18355) submitted by SNC-Lavalin on behalf of Canadian Natural Resources Limited on October 25<sup>th</sup>, 2019.

Based upon review of the information provided by the applicant, the reclamation assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 6006).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

## And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Canadian Natural Resources Limited remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

Taher Morsi, Ph.D., P.Ag Environmental Management Officer Resource Development & Stewardship Branch Operational Policy & Environment Telephone: 250-794-5234 Facsimile: 250-794-5380

E-Mail: Taher.Morsi@gov.bc.ca

cc: Kathleen Juneau, SNC-Lavalin Environmental Inc, #202-10012- 97<sup>th</sup> Avenue, Fort St John, BC, V1J5P3

BC Oil & Gas COMMISSION
-------------------------

## CERTIFICATION OF RESTORATION APPLICATION FORM – PART 2 Physical Address: 6534 Airport Road, Fort St. John, B.C. V1J 4M6 Mailing Address: Bag 2, Fort St. John, B.C. V1J 2B0 Phone: (250) 794-5200



## THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.							
COMMISSION USE ONLY A							
Commission File No. or AD No.: Document:							
ADMINISTRATION							
Well Permit No.: 18355							
Well Name: CNRL GUTAH B-041-A/094-H-14		Well Location: b-041-A/94-H-14					
Petroleum Title (Permit, Lease, Number, etc): OGC File; Not Available							
Title Holder(s) (Permittee, Lessee, etc): Canadian Natural Resources Limited							
Surface Landowner: Crown		Surface Occupant: N/A					
(Attach Letter of Release)		(Attach Letter of Release)					
Applicant's Agent in Field: Zaho Matheos, M.Sc., P.Ag., CPESC – SNC Lavalin Inc.							
Name: Cindy Grieder, P.Ag.							
Company: Canadian Natural Resources Limited		Position: Reclamation Co	pordinator				
Address: Suite 2500, 855 2 <sup>nd</sup> Street S.W. City: Cal	gary		Province: AB				
Postal Code: T2P 4J8 Phone: 403-351-2468	F	ax: 403-514-7677	Email: cindy.grieder(	@cnrl.com			
Agent Signature: Saly, Mathe, M		Date: 2/19/10/18					
S1500 Application Fee Attached							
RESTORATION INFORMATION C							
Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):							
The wellsite, access road, remote borrow pit and remote DWDA are located on Crown land. The site's status is "Abandoned".							
The site is now suitable for a Certificate of Restoration Part 2 Approval.							
Details of any areas left unrestored at Landowner's request:							
Ν/Α							
					······		
Was "Approval to Construct" subject to any reclamation co	onditions	?		YES	XNO		
Reclamation Inspection Report included?							
Is this location within the Agricultural Land Reserve? If YE	S, attach	Schedule B			 N0		

APPROVAL - FOR CO	MISSION USE ONLY		D
CERTIFICATE OF RESTORATION	CERTIFICATE NO.	6006	
This is to certify that the surface of the land held in conjunction wis satisfactorily restored. Despite the issuance of this Certificate, the investigation or remedial action upon inspection of the site or file. restoration requirements for which the Applicant is subsequently held the Approval Date: $OCT 29, 2019$	e Ministry of Environment ha Issuance of this certificate of	is the authority to order furth does not relieve the Applicar	èr site
	Authorized Commission	Employee	
The personal information requested on this form is collected under the au Natural Gas Act and the Environmental Management Act. Under certain of the Freedom of Information and Protection of Privacy Act. If you have any the Corporate Services Branch, Records Administrator, in Fort St. John at	ircumstances, some information questions about the collection,	n may be released subject to the	e provisions of

.