

Date: January 24th, 2019

Storm Resources Ltd
Suite 200, 640- 5th Avenue SW
Calgary, AB T2P 3G4

Attention: Lori Gubenco, Manager

Re: Storm Resources Certificate of Restoration Application (part II) for the Well Site
SRL TSEA A-58-K/94-P-5 (WA # 18596)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 18596) submitted by SNC-Lavalin on behalf of Storm Resources Limited on December 11th, 2018.

Based upon review of the information provided by the applicant, the reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5936).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."


And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Storm Resources Limited remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

A handwritten signature in black ink, appearing to read 'Taher Morsi', written over a horizontal line.


Taher Morsi, Ph.D., P.Ag
Environmental Management Officer
Resource Development & Stewardship Branch
Operational Policy & Environment
Telephone: 250-794-5234
Facsimile: 250-794-5380

E-Mail: Taher.Morsi@gov.bc.ca

cc: Kathleen Juneau, SNC-Lavalin Environmental Inc, #202-10012- 97th Avenue,
Fort St John, BC, V1J5P3

**CERTIFICATION OF RESTORATION
APPLICATION FORM – PART 2**

Physical Address: 6534 Airport Road,
Fort St. John, B.C. V1J 4M6
Mailing Address: Bag 2, Fort St. John, B.C.
V1J 2B0
Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY			A
Commission File No. or AD No.:		Document:	
ADMINISTRATION			B
Well Permit No.: 18596			
Well Name: SRL TSEA A-058-K/094-P-05		Well Location: a-58-K/94-P-5	
Petroleum Title (Permit, Lease, Number, etc): OGC File; Not Available		9617721	
Title Holder(s) (Permittee, Lessee, etc): Storm Resources Ltd			
Surface Landowner: Crown <i>(Attach Letter of Release)</i>		Surface Occupant: N/A <i>(Attach Letter of Release)</i>	
Applicant's Agent in Field: Alana Ross, C.Tech. – SNC Lavalin Inc.			
Name: Lori Gubenco			
Company: Storm Resources Ltd		Position: Manager, Contracts	
Address: PO Box 1420, Stn M		City: Calgary	Province: Alberta
Postal Code: T2P 2L6	Phone: 403-817-6145	Fax: 403-817-6146	Email: LoriG@stormresourcesltd.com
Agent Signature: <i>Alana Ross</i>			Date: 2018-11-30
<input checked="" type="checkbox"/> \$1500 Application Fee Attached			

RESTORATION INFORMATION	C
Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location): The site and associated access road are located on Crown land. The site's status is "Abandoned". The site is now suitable for a Certificate of Restoration Part 2 Approval.	
Details of any areas left unrestored at Landowner's request: N/A	
Was "Approval to Construct" subject to any reclamation conditions? – Nothing found in OGC file.	
Reclamation Inspection Report included?	
Is this location within the Agricultural Land Reserve? <i>If YES, attach Schedule B</i>	


CERTIFICATE OF RESTORATION

CERTIFICATE NO.

5936

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

Jan 24th 2019
Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act* and the *Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.