

Date: April 12th, 2016

Kelt Exploration (LNG) Ltd Suite 300, 311 – 6th Avenue SW Calgary, AB T2P 3H2

Attention: Doug Macarthur, Vice President Operations

Re: <u>Kelt Exploration (LNG) Certificate of Restoration Application (Part-II) for the Well</u> Site Kelt LNG Et Al Doig D-62-G/94-A-16 (WA # 18712)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for the wellsite for the above referenced well authorization (WA # 18709) submitted by Highmark Environmental Services Ltd on behalf of Kelt Exploration (LNG) Ltd on January 15th, 2016.

The reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5608).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Kelt Exploration (LNG) Ltd remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

cc:

Taher Morsi, Ph.D., P.Ag

Environmental Management Officer

Telephone: 250-794-5234 Facsimile: 250-794-5380

E-Mail: Taher.Morsi@bcogc.ca


Chris Weissbach, Highmark Environmental Services Ltd, 10121-95th Avenue,

Fort St. John, BC, V1J 1H9



CERTIFICATION OF RESTORATION APPLICATION FORM – PART 2

Physical Address: 6534 Airport Road,
Fort St. John, B.C. VIJ 4M6
Mailing Address: Bag 2, Fort St. John, B.C.
VIJ 2B0
Phone: (250) 794-5200



BC Oil and Gas Commission Date Received

THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

| registered as a member in good stal | nding win an organization operating | | mbia legislature. | |
|---|--------------------------------------|-----------------------------------|--|--|
| | <u> </u> | ION USE ONLY | | |
| Commission File No.:9617980 | Document: | ISTRATION | B | |
| Well Permit No.: 18712 | | | <u> </u> | |
| Well Name: Kelt (LNG) ET AL I | noig | Well Location: D -062 | 2-G/09/- A-16 | |
| Petroleum Title (Permit, Lease, | | VVCI) LOCABOTI, D -002 | : | |
| | | | | |
| Title Holder(s) (Permittee, Less | se, erc), iveria-xbiolaticu ilitinai | | | |
| Surface Landowner: BC Crown (Attach Letter of Release) | | | Surface Occupant:N/A (Attach Letter of Release) | |
| Applicant's Agent in Field | | | | |
| Name: Chris Weissbach | • | | | |
| ompany: Highmark Environmental Services Ltd. | | Position Senior Project | Position Senior Project Manager | |
| Address: 10121 - 95th Ave | City: Fort St. | John | Province: BC | |
| Postal Code:V1J 1H9 | Phone: 250-261-6994 | Fax:250-261-6928 | Email: <u>Chrisw@hesl.ca</u> | |
| Agent Signature: | NEISSBACH ST | | Date: Nov 26, 2015 | |
| \$1500 Application Fee Atta | ached | | | |
| MATERIAL STATE OF THE STATE OF | RESTORATION | N INFORMATION | | |
| Description of Area(s) Restored (| (Location, Remote Sump, Access a | nd other disturbed areas affiliat | HR OF HE DESCRIPTION AND RESERVE OF THE PROPERTY OF THE STATE OF THE S | |
| Sump: 60m x 80m. | | | | |
| | | | | |
| | | | | |
| Details of any areas left unrestore | ed at Landowner's request: | | | |
| N/A | ٠. | | | |
| | | | | |

Updated: 20 January 2014 Effective: 6 February 2014

| Was "Approval to Construct" subject to any reclamation condit | ions? | | YES X |
|--|--|---|-------------------|
| Reclamation Inspection Report included? | | | XYES [|
| Is this location within the Agricultural Land Reserve? If YES, a | ttach Schedule B | | □YES 🛛 |
| APPROVAL - FOR CO | MMISSION USE ONLY | | , D |
| CERTIFICATE OF RESTORATION | CERTIFICATE NO. | 5608 | |
| This is to certify that the surface of the land held in conjunction w satisfactorily restored. Despite the issuance of this Certificate, the investigation or remedial action upon inspection of the site or file restoration requirements for which the Applicant is subsequently | ne Ministry of Environment ha Issuance of this certificate o | s the authority to order fu loes not relieve the Appli | ırther site |
| Approval Date: April 12 2016 | Ta N | | 1 |
| | Aulhorized Commission E | Employee . | , |
| The personal information requested on this form is collected under the au Natural Gas Act and the Environmental Management Act. Under certain the Freedom of Information and Protection of Privacy Act. If you have any the Company's Societies Branch Records Administrator in Earl St. John of | circumstances, some information questions about the collection, t | may be released subject to | the provisions of |

Updated: 20 January 2014 Effective: 6 February 2014