

Date: March 7th, 2017

Cequence Energy Ltd
Suite 3100, 525-8th Avenue SW
Calgary, AB T2P 1G1

Attention: Michael Rakus

Re: Cequence Energy Certificate of Restoration Application (part II) for the Well Site Cequence Et Al Boundary 11-6-84-13 W6M (WA # 19200)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report (Schedule B) for wellsite for the above referenced well authorization (WA# 19200) submitted by Nor-Alta Environmental Services Ltd on behalf of Cequence Energy Ltd on January 23rd, 2017.

The reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5709).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."


And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Cequence Energy Ltd remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234.

Sincerely,



Taher Morsi, Ph.D., P.Ag
Environmental Management Officer
Telephone: 250-794-5234
Facsimile: 250-794-5380

E-Mail: Taher.Morsi@bcogc.ca

cc: Zhong Zheng, Nor-Alta Environmental Services Ltd, Suite 157, 9768 170 Street,
Edmonton AB, T5T 5L4



CERTIFICATION OF RESTORATION APPLICATION FORM – PART 2
 Physical Address: 6534 Airport Road,
 Fort St. John, B.C. V1J 4M6
 Mailing Address: Bag 2, Fort St. John, B.C.
 V1J 2B0
 Phone: (250) 794-5200

RECEIVED
 JAN 23 2017
 BC Oil & Gas Commission

THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY A

Commission File No.: _____ Document: _____

ADMINISTRATION B

Well Permit No.: 19200

Well Name: CEQUENCE ET AL BOUNDARY 11-6-84-13 Well Location: 11-06-084-13 W6M

Petroleum Title (Permit, Lease, Number, etc): Permit

Title Holder(s) (Permittee, Lessee, etc): Cequence Energy Ltd.

Surface Landowner: Public Land (Attach Letter of Release) Surface Occupant: N/A (Attach Letter of Release)

Applicant's Agent in Field

Name: Brittney Baert

Company: Nor-Alta Environmental Services Ltd. Position: Environmental Consultant

Address: Suite 157, 9768 - 170th Street City: Edmonton Province: Alberta

Postal Code: T5T 5L4 Phone: (780) 486-4931 Fax: (780) 486-4046 Email: bbaert@nor-alta.com

Agent Signature: Date: December 20, 2016

\$1500 Application Fee Attached

RESTORATION INFORMATION C

Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):

Surface Location: 11-06-084-13 W6M, including the CEQUENCE ET AL BOUNDARY 11-06-084-13 wellsite, the associated access road and log deck.

Details of any areas left unrestored at Landowner's request:

Not applicable.

Was "Approval to Construct" subject to any reclamation conditions? YES NO

Reclamation Inspection Report included? YES NO

Is this location within the Agricultural Land Reserve? If YES, attach Schedule B YES NO

CERTIFICATE OF RESTORATION

CERTIFICATE NO.

5709

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

March 7, 2017


Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act* and the *Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.