



Date: March 8th, 2017

Tourmaline Oil Corporation
3700-250- 6th Avenue SW
Calgary, AB T2P 3H7

Attention: Derrick Kosiorek, Construction Superintendent

Re: Tourmaline Oil Corporation Certificate of Restoration Application (Part-II) for the Well
Tourmaline Inga A-39-F/94-A-13 (WA # 19248)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 19248) submitted by NewAlta Corporation on behalf of Tourmaline Oil Corporation on December 2nd, 2016.

The reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5711).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."


And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Tourmaline Oil Corporation remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

A handwritten signature in black ink, appearing to read 'Taher Morsi', with a horizontal line drawn underneath it.

Taher Morsi, Ph.D., P.Ag

Environmental Management Officer

Telephone: 250-794-5234


Facsimile: 250-794-5380

E-Mail: Taher.Morsi@gov.bc.ca

cc: Michelle Kingsmith, Newalta Corporation, 211-11 Avenue SW., Calgary AB, T2R0C6

**CERTIFICATION OF RESTORATION
APPLICATION FORM – PART 2**

Physical Address: 6534 Airport Road,
Fort St. John, B.C. V1J 4M6
Mailing Address: Bag 2, Fort St. John, B.C.
V1J 2B0
Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY**A**

Commission File No. or AD No.:

Document:

ADMINISTRATION**B**Well Permit No.: **19248**

Well Name: Tourmaline Inga A-39-F/094-A-13

Well Location: A-39-F/094-A-13

Petroleum Title (Permit, Lease, Number, etc): 9619268

Title Holder(s) (Permittee, Lessee, etc): Tourmaline Oil Corporation

Surface Landowner: Crown Land and Silvio Salustro

(Attach Letter of Release)

Surface Occupant: NA

(Attach Letter of Release)

Applicant's Agent in Field

Name: Blake Bouzek

Company: Newalta Corporation

Position: Technical Manager

Address: 211 11th Ave SW

City: Calgary

Province: Alberta

Postal Code: T2R 0C6

Phone: 403-806-7000

Fax: 806-7244

Email: Bbouzek@newalta.com

Agent Signature:

Date: October 27, 2016

☒ \$1500 Application Fee Attached**RESTORATION INFORMATION****C**

Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):

Wellsite A-39-F/094-A-13 and Wellsite and Access Road B-38-F/094-A-13

Temporary Winter Campsite: C-72-E/094-A-13

Temporary Winter Access Road: B-38-F/094-A-13, G-38-F/094-A-13, D-39-F/094-A-13, A,B,C-49-F/094-A-13, D-50-F/094-A-13

A,B,C-60-F/094-A-13, D-51-E/094-A-13, A,B,C-61-E/094-A-13, D-62-E/094-A-13, A,B,C-72-E/094-A-13 and B-92-E/094-A-13

Details of any areas left unrestored at Landowner's request:

An attempt was made to obtain a letter of Release from Silvio Salustro. Two phone numbers were attempted on September 28, 2016 at 9:00 am (no answer) September 29, 2016 (no answer) and September 30, 2016 (no answer). A letter was sent to the address on the title on September 28, 2016 and an attempt at delivery was made. A notice card was left indicating where the item could be picked up at was left for the landowner. The Letter has yet to be picked up as of October 26, 2016.

Was "Approval to Construct" subject to any reclamation conditions?

☐ YES ☒ NO

Reclamation Inspection Report included?

☒ YES ☐ NO

Is this location within the Agricultural Land Reserve? If YES, attach Schedule B

☐ YES ☒ NO

APPROVAL – FOR COMMISSION USE ONLY

D

CERTIFICATE OF RESTORATION

CERTIFICATE NO.

5711

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

March 8th, 2017



Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act* and the *Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.