

Date: May 5th, 2016

ISH Energy Ltd
900 Macfarlane Tower, 700-4th Avenue SW
Calgary, AB T2P 3J4

Attention: Annette Nichols

Re: ISH Energy Certificate of Restoration Application (part II) for the Well Site ISH
Desan D-04-H/94-P-6 (WA # 20310)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA# 20310) submitted by Nor-Alta Environmental Services Ltd on behalf of ISH Energy Ltd on April 4th, 2016.

The reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5620).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."


And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore ISH Energy Ltd remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234.

Sincerely,

A handwritten signature in black ink, appearing to read 'Taher Morsi'. The signature is written in a cursive style with a horizontal line under the first name.


Taher Morsi, Ph.D., P.Ag
Environmental Management Officer
Telephone: 250-794-5234
Facsimile: 250-794-5380

E-Mail: Taher.Morsi@bcogc.ca

cc: Craig Nicke, Nor-Alta Environmental Services Ltd, Suite 157, 9768 170 Street,
Edmonton AB, T5T 5L4



**CERTIFICATION OF RESTORATION
APPLICATION FORM – PART 2**
Physical Address: 6534 Airport Road,
Fort St. John, B.C. V1J 4M6
Mailing Address: Bag 2, Fort St. John, B.C.
V1J 2B0
Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY			A
Commission File No.:		Document:	
ADMINISTRATION			B
Well Permit No.: 20310			
Well Name: ISH DESAN D-004-H/094-P-06		Well Location: D-004-H/094-P-06	
Petroleum Title (Permit, Lease, Number, etc): Permit			
Title Holder(s) (Permittee, Lessee, etc): ISH Energy Ltd.			
Surface Landowner: Crown <i>(Attach Letter of Release)</i>		Surface Occupant: No known occupant <i>(Attach Letter of Release)</i>	
Applicant's Agent in Field			
Name: David Sidlick			
Company: Nor-Alta Environmental Services Ltd.		Position Environmental Consultant	
Address: Suite 157, 9768 – 170 Street		City: Edmonton	Province: AB
Postal Code: T5T 5L4	Phone: (780) 486-4931	Fax: (780) 486-4046	Email: dsidlick@nor-alta.com
Agent Signature:			Date:
<input checked="" type="checkbox"/> \$1500 Application Fee Attached			

RESTORATION INFORMATION			C
Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):			
Areas being restored include the ISH DESAN D-004-H/094-P-06 wellsite and access road.			
Details of any areas left unrestored at Landowner's request:			
No areas are being left unrestored.			
Was "Approval to Construct" subject to any reclamation conditions?			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Reclamation Inspection Report included?			<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Is this location within the Agricultural Land Reserve? <i>If YES, attach Schedule B</i>			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO


CERTIFICATE OF RESTORATION

CERTIFICATE NO.

5620

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

May 5th, 2016

Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act* and the *Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.