

Date: January 16th, 2020

Shell Canada Ltd. 400-4th Ave S.W P.O. Box 100, Station M Calgary, AB T2P 3V4

Attention: Rob Gray, Decommissioning/Abandonment/Reclamation Team Lead

Re: <u>Shell Canada Certificate of Restoration Application (Part-II) for the Well Site Shell</u> <u>Sunset 09-17-79-18 W6M (WA # 20585)</u>

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report (**Schedule B**) for wellsite for the above referenced well authorization (WA # 20585) submitted by SNC-Lavalin on behalf of Shell Canada Ltd on December 6th, 2019.

Based upon review of the information provided by the applicant, the reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 6064).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Shell Canada Ltd remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

Taher Morsi, Ph.D., P.Ag Environmental Management Officer Operational Policy & Environment Resource Development & Stewardship Branch Telephone: 250-794-5234 Facsimile: 250-794-5380

E-Mail: Taher.Morsi@bcogc.ca

cc: Kathleen Juneau, SNC-Lavalin Environmental Inc, #202-10012- 97th Avenue, Fort St John, BC, V1J5P3



CERTIFICATION OF RESTORATION APPLICATION FORM – PART 2 Physical Address: 6534 Airport Road, Fort St. John, B.C. V1J 4M6 Mailing Address: Bag 2, Fort St. John, B.C.

V1J 2B0 Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

		co	MMISSIC	ON USE ONLY	A		
Commission File No. or AD No.:			Docum	ent:			
			ADMINIS	STRATION	В		
Well Permit No.: 20585							
Well Name: SHELL SUNSET 09-17-079-18			Well Location: 09-17-079-18 W6M				
Petroleum Title (Permit, Lease, Nur	mber, etc): O	GC file	; Not Av	ailable			
Title Holder(s) (Permittee, Lessee, e	etc): Shell C	anada	Limited				
Surface Landowner: Justin and Anna Sheets			Surface Occupant: Justin and Anna Sheets				
(Attach Letter of Release)			(Attach Letter of Release)				
Applicant's Agent in Field: Zaho Ma	theos, M.Sc	., P.Ag	., CPESC	C – SNC-Lavalin	Inc.		
Name: Rob Gray							
Company: Shell Canada Limited			Position: Decommissioning Abandonment and Remediation Team Lead				
Address: 400 4 th Ave, S.W. City:		Calgary		Province: AB			
Postal Code: Box 100 Station M	Phone: 403-384-5		091	Fax: N/A	Email: R.Gray@shell.com		
Agent Signature: Salue Mathcet			5-		Date: November 6, 2019		

\$1500 Application Fee Attached

RESTORATION INFORMATION

Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):

The site and associated access road are located on private land. The site's status is "Abandoned". The site is

now suitable for a Certificate of Restoration Part 2 Approval.

Details of any areas left unrestored at Landowner's request:

The access road and approach from the Braden Road, existing culvert under the access, two swing gates accessing the site and perimeter fencing around the site.

Was "Approval to Construct" subject to any reclamation conditions? - Nothing found in OGC file.	□yes ⊠no
Reclamation Inspection Report included?	YES NO
Is this location within the Agricultural Land Reserve? If YES, attach Schedule B	YES NO

Updated: 23-June-2016 Effective: 23-June-2016 С

APPROVAL – FOR COMMISSION USE ONLY						
CERTIFICATE OF RESTORATION	CERTIFICATE NO.	6064	c			
This is to certify that the surface of the land held in conjunction with, satisfactorily restored. Despite the issuance of this Certificate, the M investigation or remedial action upon inspection of the site or file. Iss restoration requirements for which the Applicant is subsequently held Approval Date: $Jem 16, 2e 2e$	linistry of Environment ha suance of this certificate of	s the authority to order further site loes not relieve the Applicant of any				
	Authorized Commission	Employee				
The personal information requested on this form is collected under the author Natural Gas Act and the Environmental Management Act. Under certain circu the Freedom of Information and Protection of Privacy Act. If you have any que the Corporate Services Branch, Records Administrator, in Fort St. John at the	imstances, some information estions about the collection,	may be released subject to the provision				

د. •