



Date: November 22nd, 2016

Mancal Energy Inc
1600, 530-8th Avenue
Calgary, AB T2P 5G2

Attention: Gary Horton

Re: Mancal Energy Certificate of Restoration Application (Part-II) for the Well Site
Mancal Boundary 01-08-85-14 W6M (WA # 22489)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment (Schedule B) Report for wellsite for the above referenced well authorization (WA # 22489) submitted by NewAlta Corporation on behalf of Mancal Energy Inc on November 3rd, 2016.

The reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5642).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."


And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Mancal Energy Inc remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

A handwritten signature in black ink, appearing to read 'Taher Morsi', written over a horizontal line.

Taher Morsi, Ph.D., P.Ag

Environmental Management Officer

Telephone: 250-794-5234


Facsimile: 250-794-5380

E-Mail: Taher.Morsi@gov.bc.ca

cc: Michelle Kingsmith, Newalta Corporation, 211-11 Avenue SW., Calgary AB,
T2R0C6

**CERTIFICATION OF RESTORATION****APPLICATION FORM – PART 2**

Physical Address: 6534 Airport Road,
Fort St. John, B.C. V1J 4M6
Mailing Address: Bag 2, Fort St. John, B.C.
V1J 2B0
Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY**A**

Commission File No. or AD No.:

Document:

ADMINISTRATION**B**Well Permit No.: **22489**

Well Name: Mancal Boundary 1-8-85-14

Well Location: 01-08-085-14 W6M

Petroleum Title (Permit, Lease, Number, etc): 9626271

Title Holder(s) (Permittee, Lessee, etc): Mancal Energy Inc.

Surface Landowner: Lorne Little

(Attach Letter of Release)

Surface Occupant: Stacy Esau

(Attach Letter of Release)

Applicant's Agent in Field

Name: Blake Bouzek

Company: Newalta Corporation

Position: Technical Manager

Address: 211 11th Ave SW

City: Calgary

Province: Alberta

Postal Code: T2R 0C6

Phone: 403-806-7000

Fax: 403-806-7244

Email: Bbouzek@newalta.com

Agent Signature: *B. Bouzek*Date: *October 25, 2016*☒ \$1500 Application Fee Attached**RESTORATION INFORMATION****C**

Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):

Lease site 01-08-085-14W6M

Access Road: 01-08-085-14W6M, 03-09-085-14W6M, 04-09-085-14W6M

Details of any areas left unrestored at Landowner's request:

NA

Was "Approval to Construct" subject to any reclamation conditions?

☐ YES ☒ NO

Reclamation Inspection Report included?

☒ YES ☐ NO

Is this location within the Agricultural Land Reserve? If YES, attach Schedule B

☒ YES ☐ NO


CERTIFICATE OF RESTORATION

CERTIFICATE NO.

5642

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

Nov 22nd, 2016
Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act* and the *Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.