

Date: January 18th, 2017

Enerplus Corporation 3000-333 7th Ave S.W Calgary, AB T2P 2Z1

Attention: J. Palmer

Re: <u>Enerplus Corporation Certificate of Restoration Application (Part-II) for the Well</u> Site Enerplus Tommy C-A26-L/94-G-9 (WA # 25045)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite (<u>Never Drilled</u>) for the above referenced well authorization (WA # 25045) submitted by Secure Energy Services Inc on behalf of Enerplus Corporation on December 28th, 2016.

The reclamation assessment report and additional information reviewed and found that the site has fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5674).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:


"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Enerplus Corporation remains liable for any contamination presently on site.

Applications & Operations Division Environmental Management and Reclamation Department MAILING 6534 Airport Rd Fort St John BC V1J 4M6

T 250.794-5200 F 250.794-5380 www.bcogc.ca

Any questions can be directed to the undersigned at (250) 794-234



Taher Morsi, Ph.D., P.Ag Environmental Management Officer Telephone: 250-794-5234 Facsimile: 250-794-5380

E-Mail: Taher.Morsi@bcogc.ca

cc: Sherry Stewart Ryan, Secure Energy Services Inc, 120-8832 Blackfoot Trail SW, Calgary, Albert T2J-3J1

1		
BC	Oil & Gas	COMMISSION

CERTIFICATION OF RESTORATION APPLICATION FORM – PART 2 Physical Address: 6534 Airport Road, Fort St. John, B.C. VIJ 4M6 Mailing Address: Bag 2, Fort St. John, B.C. VIJ 2B0 Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature. **COMMISSION USE ONLY** Α Document: Commission File No. or AD No.: **ADMINISTRATION** В Well Permit No.: 25045 Well Name: ENERPLUS TOMMY C-A026-L/094-G-09 Well Location: c-A026-L/094-G-09 Petroleum Title (Permit, Lease, Number, etc): OGC File # 9630343 Title Holder(s) (Permittee, Lessee, etc): Enerplus Corporation Surface Landowner: Crown Surface Occupant: Crown (Attach Letter of Release) (Attach Letter of Release) Applicant's Agent in Field Name: Andrew Taylor Company: SECURE Energy **Position Operations Supervisor** Address: 8832 Blackfoot Trail SE City: Calgary Province: AB Phone: 403-720-6011 Postal Code: T2J 3J1 Fax: Email: ataylor@secure-energy.com Agent Signature: Date: V \$1500 Application Fee Attached **RESTORATION INFORMATION** С Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location): The wellsite, log deck and access road were restored.

Details of any areas left unrestored at Landowner's request:

NA

Was "Approval to Construct" subject to any reclamation conditions?

Reclamation Inspection Report included?

Is this location within the Agricultural Land Reserve? If YES, attach Schedule B

YES

YES

YES

MNO

NO

(INO

APPROVAL – FOR COMMISSION USE ONLY D			
CERTIFICATE OF RESTORATION	CERTIFICATE NO. 5674		
This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.			
0	Authorized Commission Employee		
The personal information requested on this form is collected under the authority of and used for the purpose of administering the <i>Petroleum and</i> <i>Natural Gas Act and the Environmental Management Act.</i> Under certain circumstances, some information may be released subject to the provisions of the <i>Freedom of Information and Protection of Privacy Act.</i> If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.			