

Date: November 14th, 2019

Husky Oil Operations Ltd 707- 8th Avenue SW Calgary, AB T2P 1H5

Attention: Venessa Orr, Senior Remediation/Reclamation Advisor

Re: <u>Husky Oil Operations Certificate of Restoration Application (part II) for the Well Site Husky HZ Wolverine C-65-D/93-P-02 (WA # 25080)</u>

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite (**Never Drilled**) for the above referenced well authorization (WA # 25080) submitted by SynergyAspen Environmental on behalf of Husky Oil Operations Limited on November 7th, 2019.

Based upon review of the information provided by the applicant, the reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 6015).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Husky Oil Operations Limited remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

Taher Morsi, Ph.D., P.Ag Environmental Management Officer Operational Policy & Environment

Resource Development & Stewardship Branch

Telephone: 250-794-5234 Facsimile: 250-794-5390


E-Mail: Taher.Morsi@bcogc.ca

cc: Adrian Renneberg, Synergy Environmental Strategies Inc, 9904 106 Street, Fort St John, BC, V1J 1V8



CERTIFICATION OF RESTORATION APPLICATION FORM – PART 2

Physical Address: 6534 Airport Road, Fort St. John, B.C. V1J 4M6 Mailing Address: Bag 2, Fort St. John, B.C. V1J 2B0 Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature. **COMMISSION USE ONLY** Α Document: Commission File No.: В **ADMINISTRATION** Well Permit No.: 25080 Well Name: HUSKY HZ WOLVERINE Well Location: C-065-D/093-P-02 Petroleum Title (Permit, Lease, Number, etc): Title Holder(s) (Permittee, Lessee, etc): Husky Oil Operations Limited Surface Landowner: Crown Surface Occupant: Crown (Attach Letter of Release) (Attach Letter of Release) Applicant's Agent in Field Name: Tanya Allen, P.Ag Company: SynergyAspen Environmental Ltd. Position: Reclamation Advisor Address: 9904 106th St. City: Fort St. John Province: BC Fax: 250-785-1034 Postal Code: V1J 1V8 Phone: 250-785-1030 Email: tallen@synergyaspen.ca Agent Signature: Date: November 7, 2019 \$1500 Application Fee Attached RESTORATION INFORMATION C Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location): Site has been reclaimed and vegetation has been established. Details of any areas left unrestored at Landowner's request: N/A YES ⊠NO Was "Approval to Construct" subject to any reclamation conditions? Reclamation Inspection Report included?

Updated: 20 January 2014 Effective: 6 February 2014

Is this location within the Agricultural Land Reserve? If YES, attach Schedule B

YES

CERTIFICATE OF RESTORATION	CERTIFICATE NO. —	6015
This is to certify that the surface of the land held in conjunctio satisfactorily restored. Despite the issuance of this Certificate investigation or remedial action upon inspection of the site or restoration requirements for which the Applicant is subsequen	the Ministry of Environment has the file. Issuance of this certificate does	e authority to order further site not relieve the Applicant of any
Approval Bate. 100 179 / 20 (1		

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act and the Environmental Management Act.* Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act.* If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.

Updated: 20 January 2014 Effective: 6 February 2014