

Date: February 6<sup>th</sup>, 2019

Imperial Oil Ltd 505 Quarry Park Boulevard S.E. Calgary, AB T2C 5N1

Attention: Gerry Furrie

Re: <u>Imperial Oil Certificate of Restoration Application (part II) for the Well Site IMP</u> Pembina E BEG C-12-G/94-G-01 (WA# 3429)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 3429) submitted by Golder Associates Ltd on behalf of Imperial Oil Limited on January 15<sup>th</sup>, 2019.

Based upon review of the information provided by the applicant, the reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5954).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:


"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Imperial Oil Limited remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234



Taher Morsi, Ph.D., P.Ag Environmental Management Officer Resource Development & Stewardship Branch Operational Policy & Environment

Telephone: 250-794-5234 Facsimile: 250-794-5380

E-Mail: Taher.Morsi@gov.bc.ca

Jacqueline Foley, Golder Associates Ltd, 300-590 McKay Avenue, Kelowna, BC,

V1Y5A8

CC:



## CERTIFICATION OF RESTORATION APPLICATION FORM – PART 2

Physical Address: 6534 Airport Road, Fort St. John, B.C. VIJ 4M6 Mailing Address: Bag 2, Fort St. John, B.C. VIJ 2B0 Phone: (250) 794-5200 JAN 15 2019

BC Oil and Gas Commission

Date Received

THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 200 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.	13, c.
COMMISSION USE ONLY	A

Commission File No. or AD No.:				Document:					
ADMINISTRATION B									
Well Permit No.: Authorization #3429									
Well Name: IMP PEMBINA E BEG C-012-G/094-G-01				Well Location: C-012-G/094-G-01					
Petroleum Title (Permit, Lease, Number, etc):									
Title Holder(s) (Permittee, Lessee, etc): Imperial Oil Limited (formally Imperial Oil Enterprises Ltd.)									
Surface Landowner: Crown Land (Attach Letter of Release)				Surface Occupant: None (Attach Letter of Release)					
Applicant's Agent in Field									
Name: Jacqueline Foley									
Company: Golder Associates Ltd.				Position: Associate, Senior Hydrogeologist					
Address: 300 – 590 McKay Avenue City: Kelowna					Province: British Columbia				
Postal Code: V1Y 5A8 Phone: 250 860 8424 Fa			Fa	ax:	Email: jacqueline_foley@golder.com				
Agent Signature: Angul Fohr					Date: Dec 18, 2018				
\$1500 Application Fee Attached									
RESTORATION INFORMATION C									
Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):									
The Site is at C-12-G/94-G-1 in the Beg area. It is surrounded by forested lands. The lease area is about 122 m by 122 m. The primary									
access enters from the south and the alternative access enters from the southeast; a campsite area was also cleared. The site									
accesses were for winter use only and were not built up. The well was drilled and abandoned in 1974. Two cut blocks intersect									
the access roads. Reclamation work was completed in 2015 and a Site Reclamation Inspection was completed in August 2018.									
Details of any areas left unrestored at Landowner's request:									
None									
Was "Approval to Construct" subject to any reclamation conditions?							NO		
Reclamation Inspection Report included?							NO		
Is this location within the Agricultural Land Reserve? If YES, attach Schedule B							NO		

Updated: 23-June-2016 Effective: 23-June-2016

## APPROVAL - FOR COMMISSION USE ONLY

D

CERTIFICATE OF RESTORATION

CERTIFICATE NO.

5954

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

: Feb 6th 2019

Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act and the Environmental Management Act.* Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act.* If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.

Updated: 23-June-2016 Effective: 23-June-2016