

Date: October 25<sup>th</sup>, 2019

Ikkuma Resources Corporation  
3100-308- 4<sup>th</sup> Avenue SW  
Calgary, AB T2P 0H7

Attention: Environmental Coordinator

Re: Ikkuma Resources Certificate of Restoration Application (Part-II) for the Well Site Ikkuma Ekwan D-13-F/94-I-10 (WA # 6191)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 6191) submitted by Nor-Alta Environmental Services Ltd on behalf of Ikkuma Resources Corporation on September 13<sup>th</sup>, 2019.

The reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5999).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

**"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."**


And:

**"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."**

Therefore Ikkuma Resources Corporation remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

A handwritten signature in black ink, appearing to read 'Taher Morsi', with a long horizontal line extending to the left and a vertical line extending downwards from the end of the signature.

---

Taher Morsi, Ph.D., P.Ag

Environmental Management Officer  
Resource Development & Stewardship Branch  
Operational Policy & Environment  
Telephone: 250-794-5234  
Facsimile: 250-794-5390  
E-Mail: Taher.Morsi@gov.bc.ca

cc: Sabrina Chamberland, Nor-Alta, Suite 157, 9788-170 Street, Edmonton AB,  
T5T5L4



**CERTIFICATION OF RESTORATION  
APPLICATION FORM – PART 2**  
Physical Address: 6534 Airport Road,  
Fort St. John, B.C. V1J 4M6  
Mailing Address: Bag 2, Fort St. John, B.C.  
V1J 2B0  
Phone: (250) 794-5200

**RECEIVED**  
SEP 13 2019  
BC Oil and Gas Commission  
Date Received

THIS IS AN AUDITABLE DOCUMENT

*This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.*

COMMISSION USE ONLY				A
Commission File No. or AD No.:		Document:		
ADMINISTRATION				B
Well Permit No.: <b>6191</b>				
Well Name: <b>IKKUMA EKWAN D-013-F/094-I-10</b>		Well Location: <b>D-013-F/094-I-10</b>		
Petroleum Title ( <i>Permit, Lease, Number, etc</i> ): <b>Permit</b>				
Title Holder(s) ( <i>Permittee, Lessee, etc</i> ): <b>Ikkuma Resources Corporation</b>				
Surface Landowner: <b>Crown</b> <small>(Attach Letter of Release)</small>		Surface Occupant: <b>No known occupants</b> <small>(Attach Letter of Release)</small>		
Applicant's Agent in Field				
Name: <b>Craig Nickel</b>				
Company: <b>Nor-Alta Environmental Services Ltd.</b>		Position: <b>Environmental Consultant</b>		
Address: <b>157, 9768 – 170 Street</b>		City: <b>Edmonton</b>		Province: <b>Alberta</b>
Postal Code: <b>T5T 5L4</b>	Phone: <b>(780) 486-4931</b>	Fax: <b>(780) 486-4046</b>	Email: <b>cnickel@nor-alta.com</b>	
Agent Signature:			Date: <b>SEPTEMBER 9, 2019</b>	
<input checked="" type="checkbox"/> \$1500 Application Fee Attached				

RESTORATION INFORMATION				C
Description of Area(s) Restored ( <i>Location, Remote Sump, Access and other disturbed areas affiliated with this location</i> ):				
Areas to be restored include: <b>The IKKUMA EKWAN D-013-F/094-I-10 WELLSITE, CAMPSITE AND ACCESS ROAD.</b>				
Details of any areas left unrestored at Landowner's request:				
No areas are left unrestored.				
Was "Approval to Construct" subject to any reclamation conditions?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Reclamation Inspection Report included?				<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Is this location within the Agricultural Land Reserve? <i>If YES, attach Schedule B</i>				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

CERTIFICATE OF RESTORATION


CERTIFICATE NO.

5999

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

oct 25, 2019

  
Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act* and the *Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.