

Date: December 9th, 2016

Canadian Natural Resources Ltd Suite 2500, 855- 2nd Street SW Calgary, AB T2P 4J8

Attention: Ryan Okada, Lead Reclamation

Re: <u>Canadian Natural Resources Certificate of Restoration Application (part II) for the</u> Well Site CNRL Et Al Ring B-28-A/94-H-16 (WA # 8453)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 8453) submitted by SynergyAspen Environmental on behalf of Canadian Natural Resources Limited on December 8^h, 2016.

The reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5666).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Applications & Operations Division Environmental Management and Reclamation Department MAILING 6534 Airport Rd Fort St John BC V1J 4M6

T 250.794-5200 www.bcogc.ca F 250.794-5380 Therefore Canadian Natural Resources Limited remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

Taher Morsi, Ph.D., P.Ag Environmental Management Officer Telephone: 250-794-5234 Facsimile: 250-794-5380

E-Mail: Taher.Morsi@bcogc.ca

cc: Tanya Allen, Synergy Environmental Strategies Inc, 9904 106 Street, Fort St John, Bc, V1J 1V8



 $_{2}4$

CERTIFICATION OF RESTORATION APPLICATION FORM – PART 2 Physical Address: 6534 Airport Road, Fort St. John, B.C. V1J 4M6 Mailing Address: Bag 2, Fort St. John, B.C. V1J 2B0 Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

	Commission, at	the address noted	d above. This form may only be co	vironmental Management Act S.B.C. 200 mpleted by a professional or technologist legislature.	13, c.	
		COMMISSIC	IN USE ONLY		A	
Commission File No.:	D	ocument:				
ADMINISTRATION B						
Well Permit No.: 08453						
Well Name: CNRL ET AL RING B-028-A/094-H-16			Well Location: B-028-A/0	Well Location: B-028-A/094-H-16		
Petroleum Title (Permit, Lease,	Number, etc):					
Title Holder(s) (Permittee, Lessee, etc): Canadian Natural Resources Limited						
Surface Landowner: N/A (Attach Letter of Release)			Surface Occupant: N/A (Attach Letter of Release)			
Applicant's Agent in Field						
Name: Tanya Allen, B.Sc., P.Ag						
Company: SynergyAspen Environmental			Position: Technical Reclamation Advisor			
Address: 9904 106 th St. City: Fort St. Joh			ohn	Province: BC		
Postal Code: V1J 1V8	Phone: 250-78	35-1030	Fax: 250-785-1034	Email: tallen@synergyaspen.ca		
Agent Signature: Date: December 2, 2016						
\$1500 Application Fee Attac	ched					
RESTORATION INFORMATION C						
Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location): The wellsite is 120 m x 120 m in size and is located outside the agricultural land reserve on Crown land. A 10 m x 60 m trailersite and a 20 m x 1.31 km access road were constructed in association with the Site. A 90 m x 60 m borrow pit/remote sump area located approximately 200 m west of the site was reclaimed in association with this Site, although it was not identified on the survey plan. No other ancillary sites were constructed or affiliated with the wellsite. It SynergyAspen's opinion that the wellsite and associated ancillary sites have been satisfactorily restored and that no further work is required at the Site.						
Details of any areas left unrestored at Landowner's request:						

N/A

Was "Approval to Construct" subject to any reclamation conditions?	□yes ⊠no					
Reclamation Inspection Report included?						
Is this location within the Agricultural Land Reserve? If YES, attach Schedule B	TYES NO					
APPROVAL – FOR COMMISSION USE ONLY						
CERTIFICATE OF RESTORATION CERTIFICATE NO.	5666					
This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.						
The personal information requested on this form is collected under the authority of and used for the purpose of ad Gas Act and the Environmental Management Act. Under certain circumstances, some information may be release Freedom of Information and Protection of Privacy Act. If you have any questions about the collection, use or discle Corporate Services Branch, Records Administrator, in Fort St. John at the address above.	ed subject to the provisions of the					

Updated: 20 January 2014 Effective: 6 February 2014

نې .