



Date: May 11<sup>th</sup>, 2016

Endurance Energy Ltd  
Suite 400 444 5th Avenue SW  
Calgary, Alberta. T2P 2T8

Attention: Alan Fritz, HSE and Integrity Manager

Re: Endurance Energy Certificate of Restoration Application (Part-II) for the Well Site Endurance et Al Kyklo B-70-G/94-I-11 (WA # 9315)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 9315) submitted by SNC-Lavalin Environment on behalf of Endurance Energy Ltd on April 28<sup>th</sup>, 2016.

The reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5623).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

**"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."**


And:

**"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."**

Therefore Endurance Energy Ltd remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

A handwritten signature in black ink, appearing to read 'Taher Morsi', with a horizontal line underneath.

Taher Morsi, Ph.D., P.Ag

Environmental Management Officer

Telephone: 250-794-5234


Facsimile: 250-794-5380

E-Mail: [Taher.Morsi@bcogc.ca](mailto:Taher.Morsi@bcogc.ca)

cc: Alana Ross, SNC-Lavalin Environmental Inc, #202-10012- 97<sup>th</sup> Avenue, Fort  
St John, BC, V1J5P3

**CERTIFICATION OF RESTORATION  
APPLICATION FORM – PART 2**

Physical Address: 6534 Airport Road,  
Fort St. John, B.C. V1J 4M6  
Mailing Address: Bag 2, Fort St. John, B.C.  
V1J 2B0  
Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

*This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.*

**COMMISSION USE ONLY****A**

Commission File No.: Document:

**ADMINISTRATION****B**Well Permit No.: **09315**Well Name: **ENDURANCE ET AL HZ KYKLO B-070-G/094-I-11**Well Location: **b-70-G/94-I-11**

Petroleum Title (Permit, Lease, Number, etc):

Title Holder(s) (Permittee, Lessee, etc): **Endurance Energy Ltd.**Surface Landowner: **Crown**

(Attach Letter of Release)

Surface Occupant: **N/A**

(Attach Letter of Release)

Applicant's Agent in Field

Name: **Alana Ross**Company: **SNC-Lavalin Inc.**Position: **Project Manager**Address: **#202, 10012 97<sup>th</sup> Ave**City: **Fort St. John**Province: **BC**Postal Code: **V1J 5P3**Phone: **250-785-9898**Fax: **250-785-9848**Email: **Alana.Ross@sncclavalin.com**

Agent Signature:

Date: **2016-04-28**☒ \$1500 Application Fee Attached**RESTORATION INFORMATION****C**

Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):

**The site is located on Crown land, outside of the ALR. The site consists of a wellsite, access road, campsite, and temporary trailer site. Drilling waste was disposed of onsite. The status of the well is "Abandoned" on the OGC well details sheets and is considered suitable for a Certificate of Restoration Part 2 approval.**

Details of any areas left unrestored at Landowner's request:

**N/A**

Was "Approval to Construct" subject to any reclamation conditions? – None noted.

☐ YES ☒ NO

Reclamation Inspection Report included?

☒ YES ☐ NO

Is this location within the Agricultural Land Reserve? If YES, attach Schedule B

☐ YES ☒ NO


## CERTIFICATE OF RESTORATION

CERTIFICATE NO.

5623

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

May 11<sup>th</sup>, 2016

Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act* and the *Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.