

Date: December 10th, 2018

TAQA North Ltd
2100, 308-4th Avenue SW
Calgary, AB T2P 0H7

Attention: Wes Bell, Northern Environmental Coordinator

Re: TAQA North Certificate of Restoration Application (Part-II) for the Well Site TAQA North DAHL B-58-G/94-H-7 (WA # 10368)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite **(Never Drilled)** the above referenced well authorization (WA # 10368) submitted by SynergyAspen Environmental on behalf of TAQA North Ltd on December 4th, 2018.

Based upon review of the information provided by the applicant, the reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5919).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."


And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore TAQA North Ltd remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

A handwritten signature in black ink, appearing to read 'Taher Morsi'. The signature is written in a cursive style with a long vertical stroke at the end.

Taher Morsi, Ph.D., P.Ag

Environmental Management Officer
Operational Policy & Environment
Resource Development & Stewardship Branch
Telephone: 250-794-5234
Facsimile: 250-794-5390
E-Mail: Taher.Morsi@bcogc.ca

cc: Tanya Allen, Synergy Environmental Strategies Inc, 9904 106 Street, Fort St
John, BC, V1J 1V8



**CERTIFICATION OF RESTORATION
APPLICATION FORM – PART 2**
Physical Address: 6534 Airport Road,
Fort St. John, B.C. V1J 4M6
Mailing Address: Bag 2, Fort St. John, B.C.
V1J 2B0
Phone: (250) 794-5200

RECEIVED
DEC 04 2018
BC Oil and Gas Commission
Date Received

THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY

A

Commission File No.: Document:

ADMINISTRATION

B

Well Permit No.: **10368**

Well Name: TAQA NORTH DAHL

Well Location: B-058-G/094-H-07

Petroleum Title (*Permit, Lease, Number, etc*):

Title Holder(s) (*Permittee, Lessee, etc*): TAQA North Ltd.

Surface Landowner: Crown
(*Attach Letter of Release*)

Surface Occupant: N/A
(*Attach Letter of Release*)

Applicant's Agent in Field

Name: Tanya Allen, P.Ag

Company: SynergyAspen Environmental

Position: Environmental Client Manager

Address: 9904 106th St.

City: Fort St. John

Province: BC

Postal Code: V1J 1V8

Phone: 250-785-1030

Fax: 250-785-1034

Email: tallen@synergyaspen.ca

Agent Signature:

Date: November 14, 2018

\$1500 Application Fee Attached

RESTORATION INFORMATION

C


Description of Area(s) Restored (*Location, Remote Sump, Access and other disturbed areas affiliated with this location*):

The wellsite is 120 m x 120 m in size and is located outside the agricultural land reserve on Crown land. A 15 m x 120 m access road was constructed exclusively for winter use. A 30 m x 60 m campsite was constructed for the wellsite. The site is located within a mixed boreal forest. It is the opinion of SynergyAspen that the wellsite, access road and remote sump have been satisfactorily restored and no further work is required at the site.

Details of any areas left unrestored at Landowner's request:

N/A

Was "Approval to Construct" subject to any reclamation conditions?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Reclamation Inspection Report included?	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Is this location within the Agricultural Land Reserve? <i>If YES, attach Schedule B</i>	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

APPROVAL – FOR COMMISSION USE ONLY		D
CERTIFICATE OF RESTORATION	CERTIFICATE NO.	<u>5919</u>
<p>This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.</p>		
Approval Date:	<u>Dec 10th, 2018</u>	 Authorized Commission Employee
<p>The personal information requested on this form is collected under the authority of and used for the purpose of administering the <i>Petroleum and Natural Gas Act and the Environmental Management Act</i>. Under certain circumstances, some information may be released subject to the provisions of the <i>Freedom of Information and Protection of Privacy Act</i>. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.</p>		