

Date: December 13th, 2018

Canadian Natural Resources Ltd Suite 2500, 855- 2nd Street SW Calgary, AB T2P 4J8

Attention: Cindy Grieder, Reclamation Coordinator

Re: Canadian Natural Resources Certificate of Restoration Application (part II) for the Well Site CNRL HZ Helmet C-42-I/94-P-14 (WA # 11071)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 11071) submitted by SNC-Lavalin on behalf of Canadian Natural Resources Limited on December 3rd, 2018.

The reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5924).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Canadian Natural Resources Limited remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

Taher Morsi, Ph.D., P.Ag

Environmental Management Officer

Environmental Management & Reclamation Department

Operational Policy & Environment

Telephone: 250-794-5234 Facsimile: 250-794-5380

E-Mail: Taher.Morsi@gov.bc.ca

cc: Kathleen Juneau, SNC-Lavalin Environmental Inc, #202-10012- 97th Avenue,

Fort St John, BC, V1J5P3



CERTIFICATION OF RESTORATION APPLICATION FORM – PART 2

Physical Address: 6534 Airport Road, Fort St. John, B.C. V1J 4M6 Mailing Address: Bag 2, Fort St. John, B.C. V1J 2B0 Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY A					
Commission File No. or AD No.: Document: ADMINISTRATION B					
Well Permit No.: 11071		TRATION		Ь	
Well Perfill No.: 110/1					
Well Name: CNRL HZ HELMET C- 042-I/094-P-14		Well Location: C- 042-I/094-P-14			
Petroleum Title (Permit, Lease, Number, etc): OGC File; Not Available					
Title Holder(s) (Permittee, Lessee, etc): Canadian Natural Resources Limited					
Surface Landowner: Crown		Surface Occupant: N/A	Surface Occupant: N/A		
(Attach Letter of Release)		(Attach Letter of Release)			
Applicant's Agent in Field: Tina Harms, M.Sc., P.Ag. – SNC Lavalin Inc.					
Name: Cindy Grieder, P.Ag.					
Company: Canadian Natural Resources Limited		Position: Reclamation Coordinator			
Address: Suite 2500, 855 2 nd Street S.W. City: Calgary			Province: Alberta		
Postal Code: T2P-4J8 Phone: 403-513-2468 Fa		Fax: 403-514-7677	Email: cindy.grieder@cnrl.com		
Agent Signature:			Date: 2018-11-30		
\$1500 Application Fee Attached					
RESTORATION INFORMATION				С	
Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):					
The site and associated borrow pit and campsite are located on Crown land. The site's status is "Abandoned" and is now					
suitable for a Certificate of Restoration – Part 2 Approval.					
			,		
Details of any areas left unrestored at Landowner's request:					
N/A					
	5.		***		
Was "Approval to Construct" subject to any reclamation conditions? – Nothing found in OGC file YES NO					
Was "Approval to Construct" subject to any reclamation conditions? – Nothing found in OGC file				ОИ	
Reclamation Inspection Report included?				NO	
Is this location within the Agricultural Land Reserve? If YES, attach Schedule B				OND	

Updated: 23-June-2016 Effective: 23-June-2016

APPROVAL - FOR COMMISSION USE ONLY

)

CERTIFICATE OF RESTORATION

CERTIFICATE NO.

5924

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act and the Environmental Management Act.* Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act.* If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.

Updated: 23-June-2016 Effective: 23-June-2016