

Date: April 17th, 2018

Canadian Natural Resources Ltd Suite 2500, 855- 2nd Street SW Calgary, AB T2P 4J8

Attention: Ryan Okada, Lead Reclamation

Re: <u>Canadian Natural Resources Certificate of Restoration Application (part II) for the Well Site CNRL Et Al Helmet B-35-G/94-p-07 (WA # 11885)</u>

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 11885) submitted by SNC-Lavalin on behalf of Canadian Natural Resources Limited on April 12th, 2018.

The reclamation assessment report reviewed and found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5868).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Canadian Natural Resources Limited remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

cc:

Taher Morsi, Ph.D., P.Ag

Environmental Management Officer

Resource Development & Stewardship Branch

Operational Policy & Environment

Telephone: 250-794-5234 Facsimile: 250-794-5380

E-Mail: Taher.Morsi@gov.bc.ca

Kathleen Juneau, SNC-Lavalin Environmental Inc, #202-10012- 97th Avenue,

Fort St John, BC, V1J5P3



CERTIFICATION OF RESTORATION APPLICATION FORM – PART 2

Physical Address: 6534 Airport Road, Fort St. John, B.C. V1J 4M6 Mailing Address: Bag 2, Fort St. John, B.C. V1J 2B0 Phone: (250) 794-5200



A

THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist

COMMISSION USE ONLY

registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

Commission File No. or AD No.:		-	Document:					
ADMINISTRATION B								
Well Permit No.: 11885								
Well Name: CNRL ET AL HELMET B-035-G/094-P-07			Well Location: b-35-G/94	Well Location: b-35-G/94-P-7				
Petroleum Title (Permit, Lease, Number, etc): OGC File; Not Available								
Title Holder(s) (Permittee, Lessee, etc): Canadian Natural Resources Limited								
Surface Landowner: Crown			Surface Occupant: N/A	Surface Occupant: N/A				
(Attach Letter of Release)			(Attach Letter of Release)					
Applicant's Agent in Field: Alana Ross, C.Tech - Reclamation Specialist								
Name: Cindy Grieder	01							
Company: Canadian Natural R	esources Limi	ted	Position: Coordinator, R	Position: Coordinator, Reclamation				
Address: Suite 2500, 855 2 nd Street S.W. City: Calgary				Province: Alberta				
Postal Code: T2P 4J8 Phone: 403-513-2468 Fa			Fax: 403-514-7677	Email: cindy.grieder@cnrl.com				
Agent Signature:	fer			Date: 2018 - 04-05				
\$1500 Application Fee Attached								
		RESTORATION	INFORMATION		C			
Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):								
The site, associated borrow pit, remote DWDA and access road are located on Crown land. The site's status is "Abandoned".								
The site is now available for a Certificate of Restoration Part 2 Approval.								
Details of any areas left unrestored at Landowner's request:								
N/A								
					-			
3.	18.			(9)				
Was "Approval to Construct" subject to any reclamation conditions? – nothing found in OGC file								
Reclamation Inspection Report included?								
					YES NO			

Updated: 23-June-2016 Effective: 23-June-2016

APPROVAL – FOR COMMISSION USE ONLY							
CERTIFICATE OF RESTORATION	CERTIFICATE NO.	5868					
This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.							
Approval Date: April 17 2018	(a)	The state of the s					
	Authorized Commissi	ion Employee					
The personal information requested on this form is collected under the authority of and used for the purpose of administering the Petroleum and							

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act and the Environmental Management Act.* Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act.* If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.

Updated: 23-June-2016 Effective: 23-June-2016