

Date: August 28th, 2017

Shell Canada Ltd
400-4th Ave S.W
Calgary, AB T2P 2H5

Attention: Darren Mason, DAR Legacy Project Engineer

Re: Shell Canada Certificate of Restoration Application (Part-II) for the Well Site Shell Septimus 14-22-81-18 W6M (WA# 12195) and Shell Septimus A14-22-81-18 W6M (WA # 12730)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment (Schedule B) Report for the above referenced wells authorization (WA # 12195 and WA # 12730) located at the same location lease submitted by Secure Energy Services Inc on behalf of Shell Canada Ltd on August 28th, 2017.

The reclamation assessment report was reviewed and found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5737).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."


And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Shell Canada Ltd remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-234

Sincerely,



Taher Morsi, Ph.D., P.Ag
Environmental Management Officer
Operational Policy & Environment
Resource Development & Stewardship Branch
Telephone: 250-794-5234
Facsimile: 250-794-5380

E-Mail: Taher.Morsi@bcogc.ca

cc: Sherry Stewart Ryan, Secure Energy Services Inc, 120-8832 Blackfoot
Trail SW, Calgary, Albert T2J-3J1



**CERTIFICATION OF RESTORATION
APPLICATION FORM – PART 2**

Physical Address: 6534 Airport Road,
Fort St. John, B.C. V1J 4M6
Mailing Address: Bag 2, Fort St. John, B.C.
V1J 2B0
Phone: (250) 794-5200

Date Received

THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY		A
Commission File No.:	Document:	
ADMINISTRATION		B
Well Permit No.: 12195 & 12730		
Well Name: SHELL SEPTIMUS 14-22-081-18, SHELL SEPTIMUS A14-081-18	Well Location: 14-22-081-18 W6M	
Petroleum Title (Permit, Lease, Number, etc): N/A		
Title Holder(s) (Permittee, Lessee, etc): Shell Canada Limited		
Surface Landowner: Private – Nil Ray Farms <i>(Attach Letter of Release)</i>	Surface Occupant: N/A <i>(Attach Letter of Release)</i>	
Applicant's Agent in Field		
Name: Sherry Stewart Ryan		
Company: SECURE Energy (Onsite Services) Inc.		Position: Project Manager
Address: 8832 Blackfoot Trail SE	City: Calgary	Province: AB
Postal Code: T2J 3J1	Phone: 403.206.9882	Fax:
Agent Signature:		Email: sstewart@secure-energy.com
Date: June 29, 2017		
<input checked="" type="checkbox"/> \$1500 Application Fee Attached		
RESTORATION INFORMATION		C
Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):		
Wellsite (120 m x 128.80 m), revised access road (137 m x 15 m), remote sump (80 m x 80 m), borrow pit (25 m x 50 m)		
Details of any areas left unrestored at Landowner's request:		
The surveyed access follows an existing trail and remains in place; the borrow pit appears stable, well vegetated (banks) and is holding Water.		
Was "Approval to Construct" subject to any reclamation conditions? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		
Reclamation Inspection Report included? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		
Is this location within the Agricultural Land Reserve? If YES, attach Schedule B <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		

Updated: 20 January 2014
Effective: 6 February 2014

CERTIFICATE OF RESTORATION


CERTIFICATE NO.

5737

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

August 28th, 2017



Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act and the Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.