

Date: February 9th, 2018

Canadian Natural Resources Ltd
Suite 2500, 855- 2nd Street SW
Calgary, AB T2P 4J8

Attention: Ryan Okada, Lead Reclamation

Re: Canadian Natural Resources Certificate of Restoration Application (part II) for the Well Site CNRL Et Al Chicken C-76-B/94-G-06 (WA # 13049)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 13049) submitted by SynergyAspen Environmental on behalf of Canadian Natural Resources Limited on January 2nd 2018.

The reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5788).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."


And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Canadian Natural Resources Limited remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

A handwritten signature in black ink, appearing to read 'Taher Morsi', is written over a horizontal line.


Taher Morsi, Ph.D., P.Ag
Environmental Management Officer
Operational Policy & Environment
Resource Development & Stewardship Branch
Telephone: 250-794-5234
Facsimile: 250-794-5390

E-Mail: Taher.Morsi@bcogc.ca

cc: Shellie English, Synergy Environmental Strategies Inc, 9904 106 Street, Fort St John, BC, V1J 1V8

**CERTIFICATION OF RESTORATION
APPLICATION FORM – PART 2**

Physical Address: 6534 Airport Road,
Fort St. John, B.C. V1J 4M6
Mailing Address: Bag 2, Fort St. John, B.C.
V1J 2B0
Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY**A**

Commission File No. or AD No.:

Document:

ADMINISTRATION**B**

Well Permit No.: 13049

Well Name: CNRL et al CHICKEN C-076-B/094-G-06

Well Location: C-076-B/094-G-06

Petroleum Title (Permit, Lease, Number, etc):

Title Holder(s) (Permittee, Lessee, etc): Canadian Natural Resources Limited

Surface Landowner: Crown Land

Surface Occupant: N/A

(Attach Letter of Release) NA

(Attach Letter of Release)

Applicant's Agent in Field:

Name: Shellie English

Company: SynergyAspen Environmental Inc.

Position: Reclamation Advisor

Address: 9904 106 Street

City: Fort St. John

Province: BC

Postal Code: V1J 1V8

Phone: 250-785-1030

Fax: 250-785-1034

Email: senglish@fsjbc.com

Agent Signature:

Date: December 18, 2017

☒ \$1500 Application Fee Attached**RESTORATION INFORMATION****C****Description of Area(s) Restored** (Location, Remote Sump, Access and other disturbed areas affiliated with this location):

The wellsite was an unusual shape of 91m x 62m x 23m x 150 m x 123 m and was constructed exclusively of snow, ice and geotextile on forested, Crown land, as the site is located in a sensitive tributary/riparian area. A winter access road, 8 m in width and 2120 m in length, was associated with the wellsite. The access road was also constructed of snow, ice and geotextile material to ensure minimal disturbance in this sensitive riparian area. All snow fill and geotextile were removed and reclaimed at abandonment for both the wellsite and winter access to the satisfaction of the OGC and MOE in 2001/2002. The wellsite and access road were located out of the boundaries of the Agricultural Land Reserve. Ancillary sites associated with well location C-076-B/094-G-06 included a remote sump and a construction camp which were located adjacent to an existing PDR. The remote sump was reclaimed after the abandonment in 2002 and further work was completed in both 2013 and 2015 to address topographic/contour deficiencies. The campsite was located in a stable borrow pit along the same PDR. It is the opinion of SynergyAspen Environmental Inc. that the wellsite, access road, remote sump and campsite have been satisfactorily restored and no further work is required.

Details of any areas left unrestored at Landowner's request:

The campsite area was placed in an existing, un-reclaimed borrow pit and the area was left as such.

Was "Approval to Construct" subject to any reclamation conditions? Minimal surface disturbance for wellsite and access road was required for this project. Wellsite and access road were constructed of a "fill" of snow, ice and geotextile & reclamation involved entirely hauling away the "fill" after the well was drilled, to OGC satisfaction. All drilling material was to be hauled to the remote sump and the only disturbance was for the wellbore area, which was reclaimed.

☒ YES ☐ NO**Reclamation Inspection Report included?**☒ YES ☐ NO**Is this location within the Agricultural Land Reserve? If YES, attach Schedule B**☐ YES ☒ NO

APPROVAL – FOR COMMISSION USE ONLY

D

CERTIFICATE OF RESTORATION

CERTIFICATE NO.

5788

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

Feb 9th, 2018

Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act* and the *Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.