



Date: February 23rd, 2018

Progress Energy Canada Ltd
1600, 215 – 2nd Street S.W.
Calgary, AB
T2P 1M4

Attention: Carl Lammens, Senior Environmental Specialist

Re: Progress Energy Canada Certificate of Restoration Application (Part-II) for the Well Site Progress Et Al buckinhouse B-84-H/94-G-07 (WA # 13721)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 13721) submitted by Secure Energy Services Inc on behalf of Progress Energy Canada Ltd on January 12th, 2018.

The reclamation assessment report and additional information reviewed and found that the site has fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5823).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."


And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Progress Energy Canada Ltd remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

A handwritten signature in black ink, appearing to read 'Taher Morsi', written over a horizontal line.


Taher Morsi, Ph.D., P.Ag
Environmental Management Officer
Telephone: 250-794-5234
Facsimile: 250-794-5380

E-Mail: Taher.Morsi@bcogc.ca

cc: Sherry Stewart Ryan, Secure Energy Services Inc, 120-8832 Blackfoot
Trail SW, Calgary, Albert T2J-3J1

**CERTIFICATION OF RESTORATION
APPLICATION FORM – PART 2**

Physical Address: 6534 Airport Road,
Fort St. John, B.C. V1J 4M6
Mailing Address: Bag 2, Fort St. John, B.C.
V1J 2B0
Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY**A**

Commission File No.:

Document:

ADMINISTRATION**B**Well Permit No.: **13721**Well Name: **PROGRESS ET AL BUCKINGHORSE b-084-H/094-G-07**Well Location: **b-084-H/094-G-07**Petroleum Title (Permit, Lease, Number, etc): **WA# 13721**Title Holder(s) (Permittee, Lessee, etc): **Progress Energy Canada Ltd.**Surface Landowner: **Crown Land**

(Attach Letter of Release)

Surface Occupant:

(Attach Letter of Release)

Applicant's Agent in Field

Name: **Sherry Stewart Ryan**Company: **SECURE Energy Services Inc.**Position: **Project Manager**Address: **120 – 8832 Blackfoot Trail SW**City: **Calgary**Province: **Alberta**Postal Code: **T2J 3J1**Phone: **403-720-6011**Fax: **403-720-6007**Email: **sstewart@secure-energy.com**Agent Signature: Date: **Dec 11/17**☒ \$1500 Application Fee Attached**RESTORATION INFORMATION****C**

Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):

Well site (1.44ha), access road (0.02ha)

Details of any areas left unrestored at Landowner's request:

Remote sump, borrow pit and campsite were not utilized

Was "Approval to Construct" subject to any reclamation conditions?

☐ YES ☒ NO

Reclamation Inspection Report included?

☒ YES ☐ NO

Is this location within the Agricultural Land Reserve? If YES, attach Schedule B

☐ YES ☒ NO**APPROVAL – FOR COMMISSION USE ONLY****D**

Updated: 20 January 2014

Effective: 6 February 2014

Page 1 of 2


CERTIFICATE OF RESTORATION

CERTIFICATE NO.

5823

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

Feb 23rd, 2018
Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act* and the *Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.