

Date: February 21st, 2018

Pengrowth Energy Corporation 10228-101 Avenue Fort St John, BC V1J 2B5

Attention: Darren DuPerrier, Environmental Advisor

Re: Pengrowth Corporation Certificate of Restoration Application (Part-II) for the Well Site Pengrowth Elm A-30-F/94-H-07 (WA # 13768)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 13768) submitted by Gemini Corporation on behalf of Pengrowth Energy Corporation on November 7<sup>th</sup>, 2017.

Based upon review of the information provided by the applicant, the reclamation inspection report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5809).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore potential liability related residual contamination from the subject oil and gas activity on site remains the responsibility Pengrowth Energy Corporation

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

Taher Morsi, Ph.D., P.Ag

**Environmental Management Officer** 

Environmental Management & Reclamation Department

Operational Policy & Environment

Telephone: 250-794-5234 Facsimile: 250-794-5390

E-Mail: Taher.Morsi@bcogc.ca


cc: Wade Simpson, Gemini Corporation, 10543 100 Street, Fort St John, BC,

V1J 3Z4



## CERTIFICATION OF RESTORATION APPLICATION FORM – PART 2

Physical Address: 6534 Airport Road, Fort St. John, B.C. V1J 4M6 Mailing Address: Bag 2, Fort St. John, B.C. V1J 2B0 Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

3		CONTRACTOR OF THE PROPERTY OF	3		
COMMISSION USE ONLY					
Commission File No. or AD No.: Document:					
	ADMINIST	RATION			В
Well Permit No.: 13768					
Well Name: Pengrowth Elm		Well Location:a-30-F/94-H-7			
Petroleum Title (Permit, Lease, Number, etc):					
Title Holder(s) (Permittee, Lessee, etc): Pengrowth Energy Corporation					
Surface Landowner: N/A		Surface Occupant: N/A			
(Attach Letter of Release)	(Attach Letter of Release)				
Applicant's Agent in Field: Gemini Corporation					
Name: Wade Simpson					
Company: Gemini Corporation		Position Senior Technical Advisor			
Address: 10543 – 100 <sup>th</sup> Street City: Fort St. John		hn	Province: BC		
Postal Code: <b>V1J 3Z4</b> Phone: <b>250-263-9155</b> Fa		Fax: <b>250-263-9156</b>	Email: wade.simpson@outlook.com		
Agent Signature:		Date: October 10, 2017			
\$1500 Application Fee Attached					
RESTORATION INFORMATION					С
Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):					
Wellsite and access road.					
,					
Details of any areas left unrestored at Landowner's request:					
The site was built as surveyed and is located on Crown land. All areas associated with the site were considered satisfactorily					
reclaimed. Please refer to the Reclamation Inspection report completed by Gemini Corporation, dated October 27, 2017, for					
more detail.					
	-				
Was "Approval to Construct" subject to any reclamation conditions?					
Was "Approval to Construct" subject to any reclamati			_		
Reclamation Inspection Report included?				YES L	NO
Is this location within the Agricultural Land Reserve? If YES, attach Schedule B				□YES ×	(NO

Updated: 23-June-2016 Effective: 23-June-2016

## APPROVAL - FOR COMMISSION USE ONLY

D

**CERTIFICATE OF RESTORATION** 

CERTIFICATE NO.

5809

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

Feb 21st, 2018

Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act and the Environmental Management Act.* Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act.* If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.

Updated: 23-June-2016 Effective: 23-June-2016