

Date: February 6th, 2017

Paramount Resources Ltd
4700 Bankers Hall West
888-3rd Street, SW
Calgary, AB T2P 5C5

Attention: Geoffrey Lindsay, Team Lead-HSE Department

Re: Paramount Resources Certificate of Restoration Application (Part-II) for the Well Site PARA Bivouac D-A44-J/94-I-1 (WA # 13945)

This office has received an Application for a Certificate of Restoration (CoR-Part II) and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 13945) submitted by North Shore Environmental Consultants on behalf of Paramount Resources Ltd on December 13th 2016.

Based upon review of the information provided by the applicant, the reclamation inspection report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5694).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."


And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Paramount Resources Ltd remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,


A handwritten signature in black ink, appearing to read 'Taher Morsi', with a large loop at the end.

Taher Morsi, Ph.D., P. Ag
Environmental Management Officer
Telephone: 250-261-5710
Facsimile: 250-261-2050
E-Mail: Taher.Morsi@bcogc.ca

cc: Brent Walchuk, North Shore Environmental Consultants Inc, Suite 110, 855 –
42nd Ave SE, Calgary, AB T2G 1Y8

**CERTIFICATION OF RESTORATION
APPLICATION FORM – PART 2**

Physical Address: 6534 Airport Road,
Fort St. John, B.C. V1J 4M6
Mailing Address: Bag 2, Fort St. John, B.C.
V1J 2B0
Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY			A
Commission File No. or AD No.:		Document:	
ADMINISTRATION			B
Well Permit No.: 13945			
Well Name: PARA BIVOUAC D-A044-J/094-I-01		Well Location: D-044-J/094-I-01	
Petroleum Title (Permit, Lease, Number, etc):			
Title Holder(s) (Permittee, Lessee, etc): Paramount Resources Ltd.			
Surface Landowner: Crown Land (Attach Letter of Release)		Surface Occupant: NA (Attach Letter of Release)	
Applicant's Agent in Field			
Name: Brent Walchuk, B.Sc., P.Ag.			
Company: North Shore Environmental Consultants Inc.		Position: Remediation/Reclamation Supervisor	
Address: #143, 201 Kaska Road		City: Sherwood Park	Province: Alberta
Postal Code: T8A 2J6	Phone: 780-467-3354	Fax: 780-464-9622	Email: bwalchuk@northshoreenv.com
Agent Signature:			Date: December 1, 2016
✓ \$1500 Application Fee Attached			

RESTORATION INFORMATION		C
Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):		
The wellsite was drilled between February 14 and 30, 2011. Associated clearings included an access road and a campsite (C-043-J/094-I-01). A remote sump was surveyed adjacent to the south boundary of the wellsite and was never constructed.		
Details of any areas left unrestored at Landowner's request:		
N/A		
Was "Approval to Construct" subject to any reclamation conditions?		
		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Reclamation Inspection Report included?		
		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Is this location within the Agricultural Land Reserve? If YES, attach Schedule B		
		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO


CERTIFICATE OF RESTORATION

CERTIFICATE NO.

5694

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

Feb 6th, 2017
Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act* and the *Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.