

Date: February 1st, 2018

Paramount Resources Ltd
4700 Bankers Hall West
888-3rd Street, SW
Calgary, AB T2P 5C5

Attention: Geoffrey Lindsay, Team Lead-HSE Department

Re: Paramount Resources Certificate of Restoration Application (Part-II) for the Well Site PARA Komie B-17-G/94-O-8 (WA # 13947)

This office has received an Application for a Certificate of Restoration (CoR-Part II) and a Surface Reclamation Assessment Report for wellsite (**Never drilled**) for the above referenced well authorization (WA # 13947) submitted by North Shore Environmental Consultants on behalf of Paramount Resources Ltd on January 2nd, 2018.

Based upon review of the information provided by the applicant, the reclamation inspection report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5784).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."


And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Paramount Resources Ltd remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,


A handwritten signature in black ink, appearing to read 'Taher Morsi', written over a horizontal line.

Taher Morsi, Ph.D., P. Ag
Environmental Management Officer
Operational Policy & Environment
Resource Development & Stewardship Branch
Telephone: 250-794-5234
Facsimile: 250-794-5390
E-Mail: Taher.Morsi@bcogc.ca

cc: Brent Walchuk, North Shore Environmental Consultants Inc, #143, 201 Kaska Road, Sherwood Park, AB, T8A 2J6

**CERTIFICATION OF RESTORATION
APPLICATION FORM – PART 2**

Physical Address: 6534 Airport Road,
Fort St. John, B.C. V1J 4M6
Mailing Address: Bag 2, Fort St. John, B.C.
V1J 2B0
Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY**A**

Commission File No. or AD No.:

Document:

ADMINISTRATION**B**Well Permit No.: **13947**

Well Name: PARA KOMIE B-017-G/094-O-08

Well Location: B-017-G/094-O-08

Petroleum Title (*Permit, Lease, Number, etc*): N/ATitle Holder(s) (*Permittee, Lessee, etc*): Paramount Resources Ltd.Surface Landowner: Crown
(*Attach Letter of Release*)Surface Occupant: N/A
(*Attach Letter of Release*)

Applicant's Agent in Field

Name: Brent Walchuk

Company: North Shore Environmental Consultants Inc.

Position: Remediation/Reclamation Supervisor

Address: #143, 201 Kaska Road

City: Sherwood Park

Province: Alberta

Postal Code: T8A 2J6

Phone: (780) 467-3354

Fax: (780) 464-9622

Email: bwalchuk@northshoreenv.com

Agent Signature:

Date: December 21, 2017

✓ \$1500 Application Fee Attached

RESTORATION INFORMATION**C**Description of Area(s) Restored (*Location, Remote Sump, Access and other disturbed areas affiliated with this location*):

Associated clearings include the wellsite (B-017-G/094-O-08, Prepared but not Drilled), access road, borrow pit (not constructed, 45 m x 90 m), remote sump (45 m by 60 m), and campsite (45 m by 60 m) as per the survey plan.

Details of any areas left unrestored at Landowner's request:

N/A

Was "Approval to Construct" subject to any reclamation conditions?

☐ YES ☒ NO

Reclamation Inspection Report included?

☒ YES ☐ NOIs this location within the Agricultural Land Reserve? *If YES, attach Schedule B*☐ YES ☒ NO

CERTIFICATE OF RESTORATION

CERTIFICATE NO.

5784

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

Feb 1st 2018

Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act* and the *Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.