

Date: April 24th, 2017

Arawn Energy Ltd O/A BC0769574 BC Ltd PO Box 336 Stirling, Alberta, Canada T0K 2E0

Attention: Brian R Sumbot, Consulting Country Manager

Re:

Arawn Energy Ltd Certificate of Restoration Application (Part-II) for the Well Site Arawn S Grizzly C-43-B/93-I-15 (WA # 14004) and Arawn S Grizzly C-A43-B/93-I-15 (WA# 23808)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 14004 and WA# 23808 located at the same surafce lease) submitted by Adlard Environmental Ltd on behalf of Arawn Energy Ltd on April 13th 2017.

The reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5719).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore potential liability related residual contamination from the subject oil and gas activity remains the responsibility Arawn Energy Ltd

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

Taher Morsi, Ph.D., P.Ag

Environmental Management Officer Environmental Management & Reclamation Department

Telephone: 250-794-5234 Facsimile: 250-794-5380

E-Mail: Taher.Morsi@bcogc.ca

cc: Chris Maundrell, Adlard Environmental Ltd, PO Box 293, Charlie Lake, BC, V0C

1H0



CERTIFICATION OF RESTORATION APPLICATION FORM – PART 2

Physical Address: 6534 Airport Road, Fort St. John, B.C. V1J 4M6 Mailing Address: Bag 2, Fort St. John, B.C. V1J 2B0 Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

registered as a member in good stan	uling with an organ		ON USE ONLY	legislature.	A		
Commission File No.:	Г	ocument:	NA COL CIALT				
ADMINISTRATION B							
Well Permit No.: 14004, 23808							
Well Name: ARAWN c-43-B/93-	I-15 and c-A43-	-B/93-I-15	Well Location: c-43-B/93-	Well Location: c-43-B/93-I-15			
Petroleum Title (Permit, Lease,	Number, etc): c	-43-B/93-I-15					
Title Holder(s) (Permittee, Lesse	ee, etc): Arawn l	Energy					
Surface Landowner: Her Majest (Attach Letter of Release)	y the Queen		Surface Occupant: Her M (Attach Letter of Release)	Surface Occupant: Her Majesty the Queen (Attach Letter of Release)			
Applicant's Agent in Field: Brian Sumbot							
Name: Brian Sumbot							
Company: Arawn Energy O/A B	C0769574 BC L	_td	Position: Consultant in Co	Position: Consultant in Country Manager			
Address: PO Box 336		City: Stirling		Province: Alberta			
Postal Code: T0K 2E0	ostal Code: T0K 2E0 Phone: 403 330 8484		Fax:888-334-4927	Email: brian.r.sumbot@atlas- canamerica.net			
Agent Signature: DN: cn=Bria ou, email=b canamerica			signed by Brian Sumbot Brian Sumbot, o=Atlas CanAm, il=brian.r.sumbot@atlas- rica.net, c=CA 16.06.27 22:31:15 -06'00'	Date:2016-06-27			
\$1500 Application Fee Attached							
RESTORATION INFORMATION C							
Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):							
Arawn c-43-B/93-I-15 wellsite, a	ccess road, and	l associated b-34	-B/93-I-15 remote sump site				
Details of any areas left unrestored at Landowner's request:							
N/A							

Updated: 20 January 2014 Effective: 6 February 2014

Was "Approval to Construct" subject to any reclamation conditions?	YES	\square N					
Reclamation Inspection Report included?							
Is this location within the Agricultural Land Reserve? If YES, attach Schedule B							
APPROVAL – FOR COMMISSION USE ONLY D							
CERTIFICATE OF RESTORATION CERTIFICATE NO. 57/9							
This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission. Approval Date: April 24217							
Authorized Commission Employee							
The personal information requested on this form is collected under the authority of and used for the purpose of administering the <i>Petr Natural Gas Act and the Environmental Management Act</i> . Under certain circumstances, some information may be released subject to the <i>Freedom of Information and Protection of Privacy Act</i> . If you have any questions about the collection, use or disclosure of this information are protected administrator, in Fort St. John at the address above.	the provisions	s of act					

Updated: 20 January 2014 Effective: 6 February 2014