

August 31<sup>st</sup>, 2016

Nexen Energy ULC  
801- 7<sup>th</sup> Avenue SW.  
Calgary, AB  
T2P 3P7

Attention: David Edwards

Nexen Energy Certificate of Restoration Application (Part II) for the Well Site  
Nexen Energy TSOO d-75-H/94-J-13 (WA # 14601)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 14601) submitted by Secure Energy Services Inc on behalf of Nexen Energy on August 30<sup>th</sup>, 2016.

The reclamation inspection assessment report and additional information were reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5634).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

**“The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued.”**


And:

**“A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site.”**

Therefore Nexen Energy remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-234

Sincerely,

A handwritten signature in black ink, appearing to read 'Taher Morsi'. The signature is written in a cursive style with a long vertical stroke at the end.

---

Taher Morsi, Ph.D., P.Ag  
Environmental Management Officer  
Environmental Management & Reclamation Department  
Telephone: 250-794-5234  
Facsimile: 250-794-5380

E-Mail: [Taher.Morsi@bcogc.ca](mailto:Taher.Morsi@bcogc.ca)

cc: Calla Turnbull, Secure Energy Services Inc, 120-8832 Blackfoot Trail SW,  
Calgary, Albert T2J-3J1



**CERTIFICATION OF RESTORATION  
APPLICATION FORM – PART 2**

Physical Address: 6534 Airport Road,  
Fort St. John, B.C. V1J 4M6  
Mailing Address: Bag 2, Fort St. John, B.C.  
V1J 2B0  
Phone: (250) 794-5200

|               |
|---------------|
| Date Received |
|---------------|

THIS IS AN AUDITABLE DOCUMENT

*This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.*

**COMMISSION USE ONLY** A

Commission File No.: \_\_\_\_\_ Document: \_\_\_\_\_

**ADMINISTRATION** B

Well Permit No.: **14601**

Well Name: Nexen Energy Tsoo d-075-H/094-J-13      Well Location: d-075-H/094-J-13

Petroleum Title (*Permit, Lease, Number, etc*): OGC File Number 9608502

Title Holder(s) (*Permittee, Lessee, etc*): Nexen Energy ULC

Surface Landowner: Crown      Surface Occupant: None  
*(Attach Letter of Release)*      *(Attach Letter of Release)*

Applicant's Agent in Field

Name: Sherry Stewart-Ryan

Company: SECURE Energy (Onsite Services) Inc.      Position: Operations Supervisor

Address: 120, 8832 Blackfoot Trail SE      City: Calgary      Province: Alberta

Postal Code: T2J 3J1      Phone: 403-720-6011      Fax: 403-720-6007      Email: sstewart@secure-energy.com

Agent Signature: \_\_\_\_\_      Date: *Aug 19/16*

\$1500 Application Fee Attached

**RESTORATION INFORMATION** C

Description of Area(s) Restored (*Location, Remote Sump, Access and other disturbed areas affiliated with this location*):

The Reclamation Site Assessment (Appendix F) found that landscape and soil quality assessment met the reclamation criteria for the 120 m<sup>2</sup> wellsite and 30 x 40 m log deck. Professional rationale, in addition to 3<sup>rd</sup> party trespassing, is used to justify the presence of A sparsely vegetated area southwest of well centre.

Details of any areas left unrestored at Landowner's request:

Was "Approval to Construct" subject to any reclamation conditions?       YES     NO

Reclamation Inspection Report included?       YES     NO

Is this location within the Agricultural Land Reserve? *If YES, attach Schedule B*       YES     NO

CERTIFICATE OF RESTORATION

CERTIFICATE NO.

5634

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

Aug 31<sup>st</sup>, 2016  
Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act* and the *Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.