

Date: December 6th, 2018

ARC Resources Ltd Suite 1200-308- 4th Avenue SW Calgary, AB T2P 0H7

Attention: Mark Roblin, Environmental Coordinator

Re: <u>ARC Resources Certificate of Restoration Application (Part-II) for the Well</u> Site ARCRes Et Al DOE 13-34-80-14 W6M (WA # 15111)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment (Schedule B) Report for wellsite for the above referenced well authorization (WA # 15111) submitted by Vertex professional Services Ltd on behalf of ARC Resources Ltd on November 21st, 2018.

Based upon review of the information provided by the applicant, the reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5912).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore ARC Resources Ltd remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

Taher Morsi, Ph.D., P.Ag

Environmental Management Officer Resource Development & Stewardship Branch Operational Policy & Environment

Telephone: 250-794-5234 Facsimile: 250-794-5390

E-Mail: Taher.Morsi@gov.bc.ca


cc: Mallory Jackson, Vertex Professional Services Ltd, 161.2055 Premier Way, Sherwood Park, Alberta T8H 0G2



CERTIFICATION OF RESTORATION APPLICATION FORM - PART 2

Physical Address: 6534 Airport Road, Fort St. John, B.C. V1J 4M6 Mailing Address: Bag 2, Fort St. John, B.C. V1J 2B0

Phone: (250) 794-5200



				THIS IS AN AUDITABLE DOCUMENT	
	s Commission, at the addre	ess noted a	bove. This form may only b	e Environmental Management Act S.B.C. 2003, c. be completed by a professional or technologist mbia legislature.	
	CON	MISSION	USE ONLY	A	
Commission File No. or AD No.:			Document:		
	Andrew Market Programme	ADMINISTI	RATION	B	
Well Permit No.: 15111					
Well Name: ARCRES ET AL DOE 13-34-080-14			Well Location: 13-34-080-14 W6M		
Petroleum Title (Permit, Lease,	Number, etc):				
Title Holder(s) (Permittee, Lesse	e, etc): ARC Resource	s Ltd.			
Surface Landowner: Wilhelm Rath			Surface Occupant: N/A		
(Attach Letter of Release)			(Attach Letter of Release)		
Applicant's Agent in Field			<u></u>		
Name: Mallory Jackson					
Company: Vertex Professional Services Ltd.			Residon: Manager	•	
Address: 121, 2055 Premier Way City: Sherwood				Province: Alberta	
Postal Code: T8H 0G2	Phone: (780) 464-3295	; 3 A	ax: (7 20700 4-373457 4	Email: mjackson@vertex.ca	
Agent Signature: Wallandan Z			Mallory Jackson (0)	Date: NOVember 16,2018	
\$1500 Application Fee Attached \$3. Mg Nov ID 18.5					
	RESTO	RATION	HORMATION	ull tar at allower following C	
Description of Area(s) Restored	(Location, Remote Sump, A	Access and	other disturbed areas affilia	ated with this location):	
The wellsite is located at 13-34	1-080-14 W6M, approxi	mately 25	km northeast of Daws	on Creek, British Columbia, in the Peace	
Lowland Ecoregion. Results fr	om the Schedule B – S	ite Reclar	nation Assessment inc	dicate that the landscape, vegetation and	
soil parameters on the wellsite	have been adequately	/ reclaime	d		
1	,				
Details of any areas left unrestor	ed at Landowner's requ	uest:			
The approach within the lease	d area is to be left unre	estored at	the Landowner's requ	iest (Attachment 1).	
				The second secon	
Was "Approval to Construct" subject to any reclamation conditions?				☐YES ☑NO	
Reclamation Inspection Report in	ncluded?		☐YES NO		

Updated: 23-June-2016 Effective: 23-June-2016

Is this location within the Agricultural Land Reserve? If YES, attach Schedule B

XYES NO

APPROVAL - FOR COMMISSION USE ONLY					
CERTIFICATE OF RESTORATION	CERTIFICATE NO. 5912				
	the Ministry of Environment has the authority to order further site ile. Issuance of this certificate does not relieve the Applicant of any				
Natural Gas Act and the Environmental Management Act. Under certa	authority of and used for the purpose of administering the <i>Petroleum and</i> in circumstances, some information may be released subject to the provisions of any questions about the collection, use or disclosure of this information, contact n at the address above.				

Updated: 23-June-2016 Effective: 23-June-2016