

Date: February 26<sup>th</sup>, 2018

Whitecap Resources Inc  
Suite 3800, 525-8<sup>th</sup> Avenue SW  
Calgary, AB T2P 1G1

Attention: Amanda Peardon, HSE Advisor

Re: Whitecap Resources Certificate of Restoration Application (part II) for the Well Site Whitecap Et Al Boundary 08-25-86-14 W6M (WA # 01558)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 01558) submitted by SynergyAspen Environmental on behalf of Whitecap Resources Inc. on January 25<sup>th</sup>, 2018.

The reclamation assessment report reviewed and found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5831).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

**"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."**


And:

**"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."**

Therefore Whitecap Resources Inc. remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

A handwritten signature in dark ink, appearing to read 'Taher Morsi', written over a horizontal line.

Taher Morsi, Ph.D., P.Ag  
Environmental Management Officer  
Operational Policy & Environment  
Resource Development & Stewardship Branch  
Telephone: 250-794-5234  
Facsimile: 250-794-5390

E-Mail: [Taher.Morsi@bcogc.ca](mailto:Taher.Morsi@bcogc.ca)

cc: Margi Meekes, Synergy Environmental Strategies Inc, 9904 106 Street, Fort St John, BC, V1J 1V8

**CERTIFICATION OF RESTORATION  
APPLICATION FORM – PART 2**

Physical Address: 6534 Airport Road,  
Fort St. John, B.C. V1J 4M6  
Mailing Address: Bag 2, Fort St. John, B.C.  
V1J 2B0  
Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

*This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.*

**COMMISSION USE ONLY****A**

Commission File No. or AD No.:

Document:

**ADMINISTRATION****B**

Well Permit No.: 01558

Well Name: Whitecap Boundary 08-25-086-14

Well Location: 08-25-086-14

Petroleum Title (Permit, Lease, Number, etc): Whitecap Boundary 08-25-086-14

Title Holder(s) (Permittee, Lessee, etc):

Surface Landowner: Crown Land  
(Attach Letter of Release) NASurface Occupant: NA  
(Attach Letter of Release)

Applicant's Agent in Field: Shellie English (SynergyAspen Environmental Ltd)

Name: Amanda Peardon

Company: Whitecap Resources Ltd.

Position: HSE Advisor

Address: 3800, 525-8<sup>th</sup> Avenue Southwest

City: Calgary

Province: AB

Postal Code: T2P 1G1

Phone: 403 266-0767

Fax: 403 266 6975

Email: info@wcap.ca

Agent Signature:

Date: December 20, 2017

☒ \$1500 Application Fee Attached**RESTORATION INFORMATION****C**

Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):

Topographic and landscape parameters are considered comparable to the adjacent offsite control and compatible with current land-use.

At the time of the last inspection the site was well vegetated and it was estimated that the cover was in excess of 80%. The vegetation health, height, and vigour status were rated as good during the on-Site inspection. In general large bare patches were not present,

No noxious or nuisance weeds were observed at the site.

Details of any areas left unrestored at Landowner's request:

Crown Land

Was "Approval to Construct" subject to any reclamation conditions?

☐ YES ☒ NO

Reclamation Inspection Report included?

☒ YES ☐ NO

Is this location within the Agricultural Land Reserve? If YES, attach Schedule B

☐ YES ☒ NO

## APPROVAL – FOR COMMISSION USE ONLY

D

## CERTIFICATE OF RESTORATION

CERTIFICATE NO.

5831

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

Feb 26, 2018

Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act* and the *Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.