

Date: December 3rd, 2018

Husky Oil Operations Ltd
100, 110 Carleton Drive
St. Albert, AB T8N 7L1

Attention: Jill KAUFMANN

Re: Husky Oil Operations Certificate of Restoration Application (Part-II) for the Well Site Husky TH Hay D-51-A/94-I-9 (WA # 15625)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite the above referenced well authorization (WA # 15625) prepared by Navus Environmental and submitted by Ridgeline Canada Inc. on behalf of Husky Oil Operations Ltd on October 5th, 2018.

Based upon review of the information provided by the applicant, the reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5904).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."


And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Husky Oil Operations Ltd remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

A handwritten signature in black ink, appearing to read 'Taher Morsi'. The signature is written in a cursive style with a long, sweeping underline that extends to the right.

Taher Morsi, Ph.D., P.Ag

Environmental Management Officer
Operational Policy & Environment
Resource Development & Stewardship Branch
Telephone: 250-794-5234
Facsimile: 250-794-5390
E-Mail: Taher.Morsi@bcogc.ca

cc: Brad Funk, Ridgeline Canada Inc., #101, 3016-19th Street NE, Calgary, AB,
T2E6Y9



**CERTIFICATION OF RESTORATION
APPLICATION FORM – PART 2**
Physical Address: 6534 Airport Road,
Fort St. John, B.C. V1J 4M6
Mailing Address: Bag 2, Fort St. John, B.C.
V1J 2B0
Phone: (250) 794-5200

RECEIVED
OCT 05 2018
BC Oil and Gas Commission
Date Received

THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY				A
Commission File No. or AD No.:		Document:		
ADMINISTRATION				B
Well Permit No.: 15625				
Well Name: HUSKY TH HAY D-051-A/094-I-09		Well Location: D-051-A/094-I-09		
Petroleum Title (Permit, Lease, Number, etc): N/A				
Title Holder(s) (Permittee, Lessee, etc): HUSKY OIL OPERATIONS LIMITED				
Surface Landowner: BRITISH COLUMBIA CROWN LAND <i>(Attach Letter of Release)</i>		Surface Occupant: N/A <i>(Attach Letter of Release)</i>		
Applicant's Agent in Field				
Name: Brad Funk				
Company: RIDGELINE CANADA INC.		Position: GENERAL MANAGER		
Address: #101, 3016 – 19 th Street		City: CALGARY		Province: ALBERTA
Postal Code: T2E 6Y9	Phone: 403-806-2380	Fax: 403-806-2381	Email: bfunk@ridgelinecanada.com	
Agent Signature: <i>B-d/fk</i>			Date: August 31, 2018	
<input checked="" type="checkbox"/> \$1500 Application Fee Attached				

RESTORATION INFORMATION				C
Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):				
A wellsite with approximate dimensions of 100 m X 100 m (10,000 m ²) and well centre located within d-041-A/094-I-09 at				
(NAD 83) 58.547633° N 120.0017° W.				
Details of any areas left unrestored at Landowner's request:				
N/A – All affiliated areas have been reclaimed.				
Was "Approval to Construct" subject to any reclamation conditions?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Reclamation Inspection Report included?				<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Is this location within the Agricultural Land Reserve? If YES, attach Schedule B				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

CERTIFICATE OF RESTORATION

CERTIFICATE NO.

5904

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

Dec 3rd, 2018
Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act and the Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.