

Date: January 20th, 2020

Cenovus Energy Inc. 500 Center Street SE PO Box 766 Calgary, AB T2P 0M5

Attention: Sean Wakulchyk, Reclamation Coordinator

Re: <u>Cenovus Energy Certificate of Restoration Application (part II) for the Well Site</u> CVE Energy Et Al Noel D-06-K/93-P-01 (WA # 16376)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 16376) submitted by Millennium EMS Solutions Ltd on behalf of Cenovus Energy Inc. on December 20th, 2019.

Based upon review of the information provided by the applicant, the reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 6075).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Cenovus Energy Inc. remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

Taher Morsi, Ph.D., P.Ag
Environmental Management Officer
Environmental Management & Reclamation Department
Operational Policy & Environment

Telephone: 250-794-5234 Facsimile: 250-794-5390

E-Mail: Taher.Morsi@bcogc.ca

cc: Stacey Ingram, Millennium EMS Solutions Ltd, #102, 11312- 98th Avenue, Grande Prairie, AB T8V 8H4



CERTIFICATION OF RESTORATION APPLICATION FORM – PART 2

Physical Address: 6534 Airport Road, Fort St. John, B.C. V1J 4M6 Mailing Address: Bag 2, Fort St. John, B.C. V1J 2B0

Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY

Commission File No. or AD No.:				Document:						
ADMINISTRATION B										
Well Permit No.: 16376										
Well Name: CVE ENERGY ET AL NOEL D- 006-K/093-P-01				Well Location: D-006-K/093-P-01						
Petroleum Title (Permit, Lease,	Number, etc): O	GC File # 96129	79							
Title Holder(s) (Permittee, Lessee, etc): Cenovus Energy Inc										
Surface Landowner: Crown Land (Attach Letter of Release)				Surface Occupant: NA (Attach Letter of Release)						
Applicant's Agent in Field							79			
Name: Stacey Ingram										
Company: Millennium EMS Solutions Ltd.				Position: Environmental Scientist						
Address: #102, 11312 – 98 Avenue		City: Grande Prairie		е	Province: AB					
Postal Code: T8V 8H4	Phone: 780-35	7-5500	Fax	x:780-357-5501	Email: singram@mems.ca					
Agent Signature: \$1500 Application Fee Attached					Date: December 11, 2019					
RESTORATION INFORMATION C										
Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):										
The wellsite, adjacent borrow area, adjacent decking site and access road are associated with and included in the CoR part 2 application. The constructed borrow pit has been reclaimed with stable sloping banks which are vegetated. The utilized remote sump (b-086-K/093- P-01) is tied to b-076-K/093-P-01.										
The proposed campsite (0.24 ha), remote sump (0.36 ha) and two decking sites (0.15 ha, 0.12 ha) as referenced on the as-built survey were not constructed.										
		(t				-				
	8						8			
Was "Approval to Construct" subject to any reclamation conditions?										
Reclamation Inspection Report included?							ОИ			
Is this location within the Agricultural Land Reserve? If YES, attach Schedule B						YES 2	⊴ио			

Updated: 23-June-2016 Effective: 23-June-2016

APPROVAL – FOR COMMISSION USE ONLY D								
CERTIFICATE OF RESTORATION	CERTIFICATE NO.	_60-	15					
This is to certify that the surface of the land held in conjunction with satisfactorily restored. Despite the issuance of this Certificate, the investigation or remedial action upon inspection of the site or file. restoration requirements for which the Applicant is subsequently held. Approval Date:	Ministry of Environment hat Issuance of this certificate	as the authority to ord does not relieve the A	ler further site					
July 19, 19	Authorized Commission	Employee						

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act and the Environmental Management Act.* Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act.* If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.

Updated: 23-June-2016 Effective: 23-June-2016