

Date: June 20<sup>th</sup>, 2017

Canadian Natural Resources Ltd Suite 2500, 855- 2<sup>nd</sup> Street SW Calgary, AB T2P 4J8

Attention: Ryan Okada, Lead Reclamation

## Re: <u>Canadian Natural Resources Certificate of Restoration Application (part II) for the</u> Well Site CNRL HZ Helmet B-63-E/94-P-8 (WA # 16608)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite (<u>Never Drilled</u>) for the above referenced well authorization (WA # 16608) submitted by SNC-Lavalin on behalf of Canadian Natural Resources Limited on June 15<sup>th</sup>, 2017.

The reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5729).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Canadian Natural Resources Limited remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

Taher Morsi, Ph.D., P.Ag Environmental Management Officer Environmental Management & Reclamation Department Operational Policy & Environment Telephone: 250-794-5234 Facsimile: 250-794-5380

E-Mail: Taher.Morsi@gov.bc.ca

cc: Kathleen Juneau, SNC-Lavalin Environmental Inc, #202-10012- 97<sup>th</sup> Avenue, Fort St John, BC, V1J5P3



## CERTIFICATION OF RESTORATION APPLICATION FORM – PART 2 OGC, 100 10003 110 AVE Fort St. John, B.C. V1J 6M7 Phone: (250) 794-5200



## THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities 53, in hardcopy, to the Oil and Gas Commission, at registered as a member in good standing with an organ	the address noted	above. This form may only be co	mpleted by a professional		
COMMISSION USE ONLY					
Commission File No.: D	ocument:	A	pplication Fee: \$		
	RATION	Barris and the second	В		
Well Permit No.: 16608					
Well Name: CNRL HZ HELMET B-063-E/094-P-8		Well Location B-063-E/094-P-8			
Petroleum Title (Permit, Lease, Number, etc): O	GC File; Not ava	ilable			
Title Holder(s) (Permittee, Lessee, etc): Canadian Natural Resources Limited					
Surface Landowner: Crown (Attach Letter of Release)		Surface Occupant: N/A (Attach Letter of Release)			
Applicant's Agent in Field: Trevor McConkey, M.Sc., P.Ag. SNC-Lavalin Inc.					
Name: Ryan Okada, P.Ag., P.Bio.					
Company: Canadian Natural Resources Ltd.		Position: Lead, Reclamation			
Address: Suite 2500, 855 2 <sup>nd</sup> Street City: Calgary			Province: Alberta		
Postal Code: T2P 4J8 Phone: 403-386-5617 Fa		Fax:	Email: Ryan.Okada@cnrl.com		
Agent Signature:			Date: June 14 /2017		
RESTORATION INFORMATION C					
Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):					
This site is located on Crown land and built but not drilled. The site consists of a lease site, and access road.					
Its status is "cancelled". The site is now suitable for a Certificate of Restoration Part 2 approval.					
Details of any areas left unrestored at Landowner's request:					
N/A					
Was "Approval to Construct" subject to any reclamation conditions? - Nothing found in OGC file.				YES NO	
Reclamation Inspection Report included?				YES NO	
Is this location within the Agricultural Land Reserve? If YES, attach Schedule B				YES NO	
Updated: December, 1 2011				Page 1 of 2	

APPROVAL – FOR COMMISSION USE ONLY	D				
CERTIFICATE OF RESTORATION CERTIFICATE NO. 5729					
This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.					
Authorized Commission Employee					
The personal information requested on this form is collected under the authority of and used for the purpose of administering the <i>Petroleum and</i> <i>Natural Gas Act and the Environmental Management Act.</i> Under certain circumstances, some information may be released subject to the provisions the <i>Freedom of Information and Protection of Privacy Act.</i> If you have any questions about the collection, use or disclosure of this information, conta the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.					

alita a La segui del La segui del