

Date: February 21st, 2018

Pengrowth Energy Corporation 10228-101 Avenue Fort St John, BC V1J 2B5

Attention: Darren DuPerrier

Re: Pengrowth Corporation Certificate of Restoration Application (Part-II) for the Well Site Pengrowth Et Al Beaverdam D-37-L/94-A-16 (WA # 1746)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 1746) submitted by Gemini Corporation on behalf of Pengrowth Energy Corporation on November 7th, 2017.

Based upon review of the information provided by the applicant, the reclamation inspection report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5808).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore potential liability related residual contamination from the subject oil and gas activity on site remains the responsibility Pengrowth Energy Corporation

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

Taher Morsi, Ph.D., P.Ag

Environmental Management Officer

Environmental Management & Reclamation Department

Operational Policy & Environment

Telephone: 250-794-5234 Facsimile: 250-794-5390

E-Mail: Taher.Morsi@bcogc.ca


cc: Wade Simpson, Gemini Corporation, 10543 100 Street, Fort St John, BC,

V1J 3Z4



CERTIFICATION OF RESTORATION APPLICATION FORM – PART 2

Physical Address: 6534 Airport Road, Fort St. John, B.C. V1J 4M6 Mailing Address: Bag 2, Fort St. John, B.C. V1J 2B0 Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

registered as a member in good standing with an organization operating under an act of the british columbia registature.						
COMMISSION USE ONLY A						
Commission File No. or AD No.: Document:						
	RATION		В			
Well Permit No.: 01746						
Well Name: Pengrowth et al Beaverdam d-37-L/94-A-16		Well Location:d-37-L/94-A-16				
Petroleum Title (Permit, Lease, Number, etc):						
Title Holder(s) (Permittee, Lessee, etc): Pengrowth Energy Corporation						
Surface Landowner: N/A		Surface Occupant: N/A				
(Attach Letter of Release)		(Attach Letter of Release)	(Attach Letter of Release)			
Applicant's Agent in Field: Gemini Corporation						
Name: Wade Simpson						
Company: Gemini Corporation		Position Senior Technical Advisor				
Address: 10543 – 100 th Street C	ess: 10543 – 100 th Street City: Fort St. John		Province: BC			
Postal Code: V1J 3Z4 Phone:250-263-9	155 F	Fax: 250-263-9156	Email: wade.simpson@outlook.c	om		
Agent Signature:			Date:			
\$1500 Application Fee Attached						
\$1500 Application Fee Attached						
	STORATION II	NFORMATION		С		
			with this location):	С		
RE	ump, Access and	other disturbed areas affiliated	with this location):	С		
Description of Area(s) Restored (Location, Remote St	ump, Access and	other disturbed areas affiliated	with this location):	С		
Description of Area(s) Restored (Location, Remote St	ump, Access and	other disturbed areas affiliated	with this location):	С		
Description of Area(s) Restored (Location, Remote St	ump, Access and	other disturbed areas affiliated	with this location):	С		
Description of Area(s) Restored (Location, Remote St	ump, Access and	other disturbed areas affiliated	with this location):	С		
Description of Area(s) Restored (Location, Remote Solution) Wellsite and access road. The borrow pit was le	ump, Access and If unreclaimed	other disturbed areas affiliated				
Description of Area(s) Restored (Location, Remote Solution) Wellsite and access road. The borrow pit was le	ump, Access and off unreclaimed request: n Crown land. A	other disturbed areas affiliated . All areas associated with t	he site were considered satisfacto	rily		
Description of Area(s) Restored (Location, Remote Solution) Wellsite and access road. The borrow pit was leed to be a solution of any areas left unrestored at Landowner's the site was built as surveyed and is located on reclaimed. Please refer to the Reclamation Inspec	ump, Access and off unreclaimed request: n Crown land. A	other disturbed areas affiliated . All areas associated with t	he site were considered satisfacto	rily		
Description of Area(s) Restored (Location, Remote Solution) Wellsite and access road. The borrow pit was leed to be a solution of the borrow pit was leed	ump, Access and off unreclaimed request: n Crown land. A	other disturbed areas affiliated . All areas associated with t	he site were considered satisfacto	rily		
Description of Area(s) Restored (Location, Remote Solution) Wellsite and access road. The borrow pit was leed to be a solution of the borrow pit was leed	eft unreclaimed request: request: rection report co	other disturbed areas affiliated All areas associated with too	he site were considered satisfacto oration, dated October 30, 2017, fo	rily		
Description of Area(s) Restored (Location, Remote Solution) Wellsite and access road. The borrow pit was leed to be a solution of any areas left unrestored at Landowner's the site was built as surveyed and is located on reclaimed. Please refer to the Reclamation Inspermore detail.	eft unreclaimed request: request: rection report co	other disturbed areas affiliated All areas associated with too	he site were considered satisfacto oration, dated October 30, 2017, fo	rily r		

Updated: 23-June-2016 Effective: 23-June-2016

APPROVAL -	FOR CC	MOISSINANA	HEE ONLY
APPROVAL -	FOR CC	MAIIAII 221014	OSE CIVE!

D

CERTIFICATE OF RESTORATION

CERTIFICATE NO.

5808

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date: Feb 21, 218

Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act and the Environmental Management Act.* Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act.* If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.

Updated: 23-June-2016 Effective: 23-June-2016