

Date: February 22nd, 2018

Pengrowth Energy Corporation
10228-101 Avenue
Fort St John, BC V1J 2B5

Attention: Darren DuPerrier, Environmental Advisor

Re: Pengrowth Corporation Certificate of Restoration Application (Part-II) for the Well Site Pengrowth Aitken B-53-L/94-A-13 (WA # 17665)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for the wellsite for the above referenced well authorization (WA # 17665) submitted by Gemini Corporation on behalf of Pengrowth Energy Corporation on February 20th, 2018.

Based upon review of the information provided by the applicant, the reclamation inspection report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5817).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."


And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore potential liability related residual contamination from the subject oil and gas activity on site remains the responsibility Pengrowth Energy Corporation

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

A handwritten signature in blue ink, appearing to read 'Taher Morsi', with a horizontal line underneath.


Taher Morsi, Ph.D., P.Ag
Environmental Management Officer
Environmental Management & Reclamation Department
Operational Policy & Environment
Telephone: 250-794-5234
Facsimile: 250-794-5390

E-Mail: Taher.Morsi@bcogc.ca

cc: Vanessa James-Davies, Gemini Corporation, 10543 100 Street, Fort St John,
BC, V1J 3Z4

**CERTIFICATION OF RESTORATION
APPLICATION FORM – PART 2**

Physical Address: 6534 Airport Road,
Fort St. John, B.C. V1J 4M6
Mailing Address: Bag 2, Fort St. John, B.C.
V1J 2B0
Phone: (250) 794-5200




THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

COMMISSION USE ONLY				A
Commission File No. or AD No.:		Document:		
ADMINISTRATION				B
Well Permit No.: 17665				
Well Name: Pengrowth Aitken b-53-L/94-A-13		Well Location: b-53-L/94-A13		
Petroleum Title (Permit, Lease, Number, etc): Pengrowth Energy Corporation				
Title Holder(s) (Permittee, Lessee, etc):				
Surface Landowner: Crown Land (Attach Letter of Release)		Surface Occupant: (Attach Letter of Release)		
Applicant's Agent in Field				
Name: Vanessa James-Davies				
Company: Gemini Corporation		Position Project Manager		
Address: 10543 100 Street		City: Fort St. John		Province: BC
Postal Code: V1J 3Z4	Phone: 250-263-9155	250-263-9156	Email: vjamesdavies@geminiCorp.ca	
Agent Signature: <i>V. James-Davies</i>			Date: February 22, 2018	
<input checked="" type="checkbox"/> \$1500 Application Fee Attached				

RESTORATION INFORMATION		C
Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):		
The wellsite, access road, and decking site were built as per the Survey Plan and were considered fully restored.		
Refer to the <i>Reclamation Inspection</i> report completed by Gemini Corporation, dated December 13, 2017, for more detail.		
Details of any areas left unrestored at Landowner's request:		
The site was built on crown land.		
Was "Approval to Construct" subject to any reclamation conditions?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Reclamation Inspection Report included?		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
Is this location within the Agricultural Land Reserve? If YES, attach Schedule B		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

APPROVAL – FOR COMMISSION USE ONLY		D
CERTIFICATE OF RESTORATION	CERTIFICATE NO. <u>5817</u>	
<p>This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.</p>		
Approval Date: <u>Feb 22nd, 2018</u>	 Authorized Commission Employee	
<p>The personal information requested on this form is collected under the authority of and used for the purpose of administering the <i>Petroleum and Natural Gas Act</i> and the <i>Environmental Management Act</i>. Under certain circumstances, some information may be released subject to the provisions of the <i>Freedom of Information and Protection of Privacy Act</i>. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.</p>		